

EMERGENCY RESPONSE CENTRE EXERCISE REPORT:

18 Dec 2024 @ 1500 hrs SGT

Vessel: IVS DUNES; IMO 9838515

Flag: Singapore MPA

Class: ClassNK Nippon Kaiji Kyokai

"Explosion + Fire in the engine room. Black Out. The vessel is drifting towards Iranian waters."

NOTE:

This exercise was conducted with the vessel Master of IVS Dunes, Next of Kins, Local Agent, MRCC, P&I / H&M, Flag and Class.

1. Purpose.

- To test company and vessel readiness should an emergency occur
- To test the ability of emergency response teams to effectively work together to mitigate the effects of the incident.
- To practice coordination between the different teams such as company emergency team and outside parties on a real time basis.
- To test the 24 hours emergency number and all communication equipment
- To test Island View Shipping response to the (simulated) media.
- To assess the effectiveness of implementation of contingency plan
- To understand and evaluate logistics requirements.
- To familiarize and to rehearse key personnel of their role during an emergency.
- To identify the weakness / lapses (which can be improved later) in our system.

2. Attendees

Function	Name of Person
Management Team	Martin Henry
	Siew Fong Bong
Incident Manager	Hilton Stroebel
Incident Coordinator	Rajaraman Krishnamoorthy (Raja)
Technical	Denver Mariano
Technical Support	Rennie Govender
	Henry Dayo
	Joey Baluyot
	Reynaldo Gonzales
	Yogesh Devendra Negi
Risk	Mads Walther
Risk Support	Rajesh Sharma
	Brett McElligott
	Wu Ning (Tony)
	Liu Hai Jian (Luke)
	Deng Wen Feng (Dennis)



Crewing	Ashish Kambo
Crewing Support	Jaja Casas
Procurement Support	Karen Foroneas
	Sharo Mee Sayno
IT Support	Iyer Ramaswamy Subramani (Subu)
ERC Scribe	Felicia Hong
Scribe	Frank So

3. Exercise rule

- SAFETY FIRST. All personnel on board shall be responsible for the safe Navigation and
 Operation during exercise. If an unsafe condition or operation is discovered, ensure to notify
 the team members. The Master to determine whether the situation can be corrected and if
 exercise should continue.
- Begin and end all telephone, radio conversations and email communication with the statement "THIS IS A DRILL". Ensure this statement is included on all email exercise documents. Email subject should also contain 'DRILL'.
- RECORDS All documents and checklists exchanged by email used during the Exercise should be maintained. All details to be logged in the as evidence of the Ship Shore Exercise.
- Some external communication Agent, Port/Flag state, P&I Club and Media (MTI) during this exercise shall be done only with the "role play" person.
- In the event of a REAL EMERGENCY THIS EXERCISE WILL BE TERMINATED
- All actions taken during the exercise, time, event, and description of activity (such as telephone call or personal contact) shall be recorded.
- Debriefing shall be held in ship and office after the exercise. During this debriefing, participants shall discuss the response and identify areas that were well handled, opportunities for improvement, and suggested action items.
- The Master shall follow-up this exercise with a debriefing and evaluation, involving all the exercise participants, use Form 3.2.3

4. Scenario Summary – Exercise

"Explosion + Fire in the engine room. Black Out. The vessel is drifting towards Iranian waters"

1. Setting:

IVS Dunes is enroute fully laden from Mesaieed Port in Qatar to New Orleans in US.

2. Incident:

Explosion + Fire in the engine room. Black Out. The vessel is drifting towards Iranian waters. Injured persons in the fire:

- Chief Engineer, Nguyen Van Dung (Burn Injuries, Unconscious)
- Fourth Engineer, Nguyen Cong Anh (Burn injuries, Head and leg injuries due to fall, Conscious)

3. Development

Drifting towards shallow waters. Development of scenario iaw Captains decision and in coordination with MRCC, simulated by NHC.

Optional development:



- Medevac of injured persons to New Khasab Hospital in Oman... Is this a relevant and approved Hospital?
- JRCC Masqat Oman involved but MRCC Bandar Abbas is also eager and wants to take over operation
- Leaking Oil
- Naval vessels from both Iran and EU Operation Aspides in area. IVS Dunes is forced to abandon ship. Reluctant to do so...What to do?
- Iranian Forces to intervene. Threatening to take over IVS Dunes

Ship

Master called office using 24 hrs telephone number informing that fire and explosion in the engine room, Suspected fire started from Crank Case. No External Damage to the ship's hull at this point. Crews are busy evacuating.

Necessary notifications were made by Master and Office.

Master to update – C/E is unconscious and 4/Eng Hand and Leg Injury concussion.

- Master to initiate drill as above and call office.
- Activate security, breach of hull and fire in engine room contingency plan
- Notifications to be made in conjunction with office
- Ship loading condition Cargo, ballast, bunkers on board are to be sent to the office for damage stability assessment.
- Conduct the drill using contingency plans:
 - Security drill (damage to vessel by explosive), notifying UKMTO
 - Breach of hull / structural failure
 - Fire in Engine Room
 - Electrical Power Failure / Blackout
 - Serious Injury

Office

After Master's telephone call received by duty person, he set up MS Team consisting of ERC members for responding to emergency on board the vessel. Emergency Response Centres were set up in Singapore and Emergency Support was set up in Durban, Hong Kong, China and Manila Offices.

Communication was kept with the Master on MS Team for office support and advice. Initial and follow-up reports are to be sent using OneNote Emergency. Relevant internal and external parties are to be informed by the office response team as required.

5. Sequence of Events

<u>Date</u>	TIME	<u>Initial</u>	Event Details	<u>Action</u>
18.12.24	1509hrs		Captain Rajesh received a call from the Master of IVS Dunes	
	1524hrs		2 Crew Member injured Chief Engineer and 4th Engineer Activate Emergency Contingency Plan onboard	Raja
			MRCC informed and in touch MEDEVAC requested Hospital in Oman	Master
			Both away from scene and in ships hospital Chief Engineer unconscious 4th Engineer conscious (leg & Hand injury)	Master



			MEDEVAC abt 15min	
15	27hrs	FKHS	Master -	Master
			Alter course to away from Iranian Water	Raja
15	30hrs	FKHS	Intial email sent (Response Team)	Rajesh
15	30hrs	FKHS	Inform Agent WSS	Ashish
15	32 hrs	DVM	Technical support - Send GA plan and tank capacity plan. Crankcase explosion - The immediate response should be to shut down the engine. Inform WH and monitor any further issues. Ensure crankcase doors remain closed to prevent air ingress and potentially secondary explosion. LO circulation to keep ON to allow cooling the hot spot.	
15	33 hrs	FH	Incident coordinator interacted with incident manager	
15: 15:	34 37hrs	FKHS AK	Lost communication with Vessel Local agent in Oman WSS appointed to receive the injured crew member and transfer them to hospital in Oman.	Raja
	38hrs 39 hrs		Helicopter arrived for MEDEVAC Helicopter arrived to evacuate the injured officers	Raja
15	39hrs	FKHS	Manning Agent TMM next of kin and Company Doctor informed	Jaja
	45hrs 40H	FKHS JDC	Ambrey informed Sent email informing manning agent in Vietnam (TMM) for them to assist in informing next of kin of injured crew	Brett
15	42H	DVM	Class NK informed about the incident / look for repair yard	
15	44hrs	FKHS	Flag, MRCC, SOPEP National Contact Point being informed	Wu Ning
15	46hrs	FKHS	P&I Informed	Ashish
15	46H	JDC	Send an email to company doctor (Shipmed) requesting them to coordinate with and assist MSTR in managing situation of injured crew onboard while waiting for medevac.	
15	48hrs	RS	Sent an email to salvage company for the assistance of the tugs	Rajesh
15	50hrs	FKHS	Assessing Security Event in around vessel area	Ambrey
15	50hrs	FKHS	MRCC informed by MSI	Wu Ning
15	52hrs	FKHS	CO2 system released Fire onboard extinguish to be confirmed Anchor ready to be dropped	Mads
15	52hrs	FKHS	Flag (MPA Singapore) informed (Email)	Wu Ning
15	54hrs	FKHS	NHC informed (Email)	Wu Ning
15	54hrs	FKHS	Navigate response informed (email) to be on standby for Media Inquiry	Rajesh
15	55hrs	FKHS	PSC Informed (Email)	Wu Ning
15	55hrs	FKHS	Rajesh called Salvage (MARINT)	Rajesh
15	59hrs	FKHS	Navigate Response reverted with first draft Holding Statement	Navigate Respons
16	00hrs	JDC FKHS	Called P&I / informed them that CE already extracted from vessel Ambrey responded US Navy contacted and monitoring situation	Brett
16 16	01hrs 00	FKHS	Shipyard in Oman inquired Free space enquiry sent to Oman & Duqm shipyard for the Urgent docking space requirement	Yogesh Yogesh
16: 16:	23 03hrs	FKHS	Both Crew evacuated Stbd anchor broke	Mads
16	04hrs	FKHS	Email to Ambrey – Abandoning Vessel	Brett



Ward	Mu Ning Mads Ashish Brett Rajesh Felicia Felicia Brett
) be	Ashish Brett Rajesh Felicia
) be	Brett Rajesh Felicia
b be	Rajesh Felicia Felicia
n be	Felicia Felicia
n be	Felicia
n	
n	
n	Brett
n	+
	Ambrey
	Felicia
the	
	Brett
	Rajesh
	Liu Hai Jia
pital	Felicia
	Mads
	Brett
	Jaja
	Rajesh Wu Ning
	Mads
	Felicia
	Brett
	Brett
_	
4C –	Brett
	as as



1637hrs	FKHS	UK P&I requested to send representative to Hospital for the 2 injured Crew	Ashish
1638hrs	FKHS	No update from Tug, will continue to contact them Flag State informed to put pressure on the Iranian Worship not to seize IVS Dunes	Rajesh
1640 hrs	RS	No one responded, left a message on voice mail to tug company regarding availability of the tug	Rajesh
1640Hrs	AK	Contacted WSS- Agent Omar Ali – his representative will reach Sohar Hospital in 30 mins and will give an update on the crew members medical condition.	
1643H	FKHS	ETA in 20min (Helicopter)	Brett
1643H	JDC AK	Spoke to TMM informing them of email updates sent at 1634H Situation onboard same Received call from 4E NOK Received call from CE NOK Received call from Wiper's wife asking update on his husband's well being	Mads
1644hrs	FKHS	SITREP SIX sent to Global Emergency & NHC	Felicia
1645H	JDC	Spoke to Durban Manning Office informing them of email updates sent at 1640H	
1646hrs 1648hrs	FKHS	Marint not able to contact No response from Marint, contact another Tug Check with Ambrey for Tug assistance	Rajesh
1650hrs 1647hrs	1	Ambrey Unable to secure Helicopter Evac – Iranian taking command of vessel US Military Helicopter ooa 10 / 15min – no evacuation and agressive maneuver as not wanting to put crew / vessel at risk. Advise to crew, accept and comply with Iranian Navy to not escalate tension US Destroyer ETA 3hrs – probably cannot do anything but just on standby due to the crew involvement of Iranian Navy Informed Flag State by email the SITUATION REPORT SITREP SIX.	Brett Wu Ning
1648 hrs	AK	Received call from 4E NOK (Wife) wanting an update on his husband's condition and also asking for agents contact number.	S
1652hrs	FKHS	Ambrey Tug – assistance cannot be rendered so quickly No tug assistance	Brett
1656hrs	FKHS	Iranian Navy shot warning shot around the hull Iranian Navy boarding the ship	Mads
1657hrs	FKHS	SITREP Seven sent to Global Emergency & NHC	Felicia
1657hrs	FKHS	Ambrey ETA of tugs to assist is unrealistic and will likely be refused by Iranians. This may escalate the situation. ETA of Navy Helicopter is 10 mins however there are NO EVAC capabilities. ETA of Destroyer USS MASON is 3 hours.	Ambrey
1658hrs	FKHS	Ambrey informed (email) Iranian Navy shot warning shot around the hull Iranian Navy boarding the ship	Brett
1700hrs	FKHS	Drill End	Mads
	FKHS	SITREP FINAL sent to Global Emergency & NHC	Felicia

6. Conclusion

The Drill was discussed, and the following areas were identified for improvement.



No.	Description	Target Completion Date	Responsibility	Completion Date
01.	Time Sheet (Time Log) Needs to be re-worked	18 Dec 2024	Frank So	18 Dec 2024
	Each Time Sheet for Each Support Group.			
02.	During the workup of obtaining the Next of Kin onboard the Dunes it was noted that NO next of Kin details were available for 66% of the crew onboard.	18 Dec 2024	Crewing	18 Dec 2024
03.	"Call Out Section" requires another Flow Chart	18 Dec 2024	Brett	18 Dec 2024
04.	Appointed Agent was not shared with the Team / in OneNote Emergency	18 Dec 2024	IVS Risk	18 Dec 2024
05.	Initial Report must first be sent. After, SITREP will be sent.	18 Dec 2024	IVS Risk	18 Dec 2024
	Initial Report should always be CC'ed to the Master.			
06.	There were not enough visuals in the Emergency Room	18 Dec 2024	IVS Risk	18 Dec 2024
07.	Try to use one Application or Software for communications	18 Dec 2024	Mads	18 Dec 2024

Refer attached appendices: Appendix A – Initial report & SITREP

Appendix B - External Notifications

Appendix C - Shipboard drill report

Appendix A – Initial Report and SITREP INITIAL REPORT





All Emails are to be sent to the following address: globalerc@ivs-services.com

Emergency Contact No: Call the DPA/Marine Superintendent.

Emergency Response Initial Report:

emergency response militi	ar neport i
IMO number	9838515
Date / Time of call from vessel:	18 Dec 2024 / 1509hrs Singapore time
Who contacted the Office:	Master Capt. Nguyen Dinh Khanh
Description of Incident:	Fire and explosion in E/R, crank case explosion is suspected
Location of incident on board:	E/R
Any injuries / casualties:	C/E Nguyen Van Dung - Burn injury, Unconscientious 4/E Nguyen Cong Anh - hand and leg injury, concussion
_	They are in process of being evacuated
Damages:	No damage yet
Date / Time of incident on board:	Not yet known, Master was quite busy in dealing the situation
Ship's position:	26 - 00N, 066-37E, vessel drifting in the Iranian water
Course	
Speed	
Cargo On-board and quantity:	58071 MT
Bunker quantity on board:	Not yet known
Any Oil Spill:	No
Approx Quantity spilt over board:	Nil
Next Port and distance	New Orleans
Weather conditions:	

Reminder: Master/Office to follow the relevant contingency plan





Ship Name:	IVS DUNES
SITREP No:	01
Date and Time (UTC) of situation report	18 Dec 2024 / 1517hrs
Summary / Update of the incident	
Update of the incident	Fire and explosion in the engine room, Suspected fire started from Crank Case. No External Damage to the ship hull at this point of time. Crews are busy evacuating.
Information received from:	Master of IVS Dunes - Captain Nguyen Dinh Khanh
Number/Details of Casualties:	C/E Nguyen Van Dung he is unconscious and 4/Eng Nguyen Cong Anh Hand and Leg Injury concussion
• Damage:	Hull not reported damaged
Any external assistance required:	Helivac expected about 15 minutes, both injured officers to be sent to sohar oman hospital
Authorities Involved:	Flag state and port state
Emergency Services Involved:	MRCC
Response Services Involved:	Medivac using helicopter
Company Emergency Response Activities:	ERC activated
Press Media Coverage	Navigate Response informed
Press Response:	NIL
Report Sheet Issued By:	
Name:	RAJESH SHARMA
Title:	DPA
Contact Details:	97778773





al. N	
Ship Name:	IVS DUNES
SITREP No:	02
Date and Time (UTC) of situation report:	18 Dec 2024 / 1530hrs
Summary / Update of the incident	
Update of the incident	Both office are on Sketches
Information received from:	Master of IVS DUNES
Number/Details of Casualties:	2 of the injured officers are being evacuated by helicopter
Damage:	Crank case explosion
Any external assistance required:	
Authorities Involved:	MRCC
Emergency Services Involved:	Stowage company informed
Response Services Involved:	
Company Emergency Response Activities:	
Press Media Coverage	Media personnel all informed
Press Response:	Media Statement in preparation
Report Sheet Issued By:	
Name:	RAJESH SHARMA
Title:	DPA
Contact Details:	97778773





ALL 11	
Ship Name:	IVS DUNES
SITREP No:	03
Date and Time (UTC) of situation report:	18 Dec 2024 / 1550 hrs
Summary / Update of the incident	
Update of the incident	Helicopter 1 of 2 onboard evacuated, another in progress. CO2 released. Very Hot engine
	Room, Doors are all closed. All crews are accounted for.
Information received from:	IVS Dunes / Master
Number/Details of Casualties:	2
Damage:	Crank Case explosion
Any external assistance required:	TUG BOATS / AMBREY
Authorities Involved:	MRCC
Emergency Services Involved:	Stowage company informed
Response Services Involved:	PSC informed
Company Emergency Response Activities:	Master informed to consider anchoring
Press Media Coverage	Media personnel all informed
Press Response:	Media Statement in preparation
Report Sheet Issued By:	
Name:	RAJESH SHARMA
Title:	DPA
Contact Details:	97778773





Ship Name:	IVS DUNES
SITREP No:	04
Date and Time (UTC) of situation report:	18 Dec 2024 / 1602hrs
Summary / Update of the incident	
Update of the incident	2 of 2 injured officers evacuated safely by helicopter. Starboard Anchor released, Chain cut off and vessel lost anchor. speed reduced 0.5 knots. Situation is under control, awaiting for US navy vessel to approach. Might consider to evacuate all crews.
Information received from:	Master of IVS DUNES
Number/Details of Casualties:	2
Damage:	Crank Case explosion
Any external assistance required:	TUG BOATS / AMBREY
Authorities Involved:	PSC
Emergency Services Involved:	Stowage / salvage company informed
Response Services Involved:	MRCC
Company Emergency Response Activities:	US NAVY requested for assistance
Press Media Coverage	Informed
Press Response:	informed
Report Sheet Issued By:	
Name:	RAJESH SHARMA
Title:	DPA
Contact Details:	97778773





Ship Name:	IVS DUNES
SITREP No:	05
Date and Time (UTC) of situation report:	18 Dec 2024 / 1612hrs
Summary / Update of the incident	
Update of the incident	3 Iranian authorities boat surrounded and circling the vessel and requested to board the vessel. Captain trying to buy time, by telling authorities that they are arranging the pilot ladder etc. US Navy can only arrived in 4 hours time, therefore ambrey will arrange for helicopter to evacuate the crews.
Information received from:	Captain of IVS DUNES
Number/Details of Casualties:	2
Damage:	Crank Case explosion
Any external assistance required:	Port State
Authorities Involved:	Iranian Authority
Emergency Services Involved:	MRCC
Response Services Involved:	Ambrey
Company Emergency Response Activities:	ERC activated
Press Media Coverage	Informed
Press Response:	Waiting for statement
Report Sheet Issued By:	
Name:	FELICIA HONG
Title:	MARINE ADMINISTRATOR
Contact Details:	97773875





Ship Name:	IVS DUNES
SITREP No:	06
Date and Time (UTC) of situation report:	18 Dec 2024 / 1630hrs
Summary / Update of the incident	
Update of the incident	Waiting for US navy helicopter assistance arranged by Ambrey will arrive 30 mins to show presence. Expecting USS Mason to arrive 4 hours later. Crews are to be still remain onboard until such time. Iranians authorities are still alongside and persistent to board the vessel.
Information received from:	Captain of IVS DUNES
Number/Details of Casualties:	2
Damage:	Crank Case explosion
Any external assistance required:	Port State/ salvage / tug boat
Authorities Involved:	Iranian Authority
Emergency Services Involved:	MRCC
Response Services Involved:	Ambrey
Company Emergency Response Activities:	ERC activated
Press Media Coverage	Informed
Press Response:	Waiting for statement
Report Sheet Issued By:	
Name:	FELICIA HONG
Title:	MARINE ADMINISTRATOR
Contact Details:	97773875





Ship Name:	IVS DUNE
SITREP No:	07
Date and Time (UTC) of situation report:	18 Dec 2024 / 1640hrs
Summary / Update of the incident	
Update of the incident	Planning to send 2 towing tugs will be standby to tow the vessel in case vessel drifting to the Iranian waters. US Navy helicopter will arrive anytime to show presence. Master concerned about the towage company contract. Company will handled this. Ambrey not able to assist on tugs with such short notice, company to source for another towage company.
Information received from:	Captain of IVS DUNES
Number/Details of Casualties:	2
Damage:	Crank Case explosion
Any external assistance required:	Port State/ salvage / tug boat
Authorities Involved:	Iranian Authority
Emergency Services Involved:	MRCC
Response Services Involved:	Ambrey
Company Emergency Response Activities:	ERC activated
Press Media Coverage	Informed
Press Response:	Waiting for statement
Report Sheet Issued By:	
Name:	FELICIA HONG
Title:	MARINE ADMINISTRATOR
Contact Details:	97773875





Ship Name:	IVS DUNES
SITREP No:	FINAL
Date and Time (UTC) of situation report:	18 Dec 2024 / 1648hrs
Summary / Update of the incident	
Update of the incident	Company in the process to arrange the towing tugs, US Navy helicopter has arrived. Iranian authorities have started firing and want to board the vessel, Captain has lower the ladder for the Iranian authorities to board. Master will revert situation later.
Information received from:	Captain of IVS DUNES
Number/Details of Casualties:	2
Damage:	Crank Case explosion
Any external assistance required:	Port State/ salvage / tug boat
Authorities Involved:	Iranian Authority
Emergency Services Involved:	MRCC
Response Services Involved:	Ambrey
Company Emergency Response Activities:	ERC activated
Press Media Coverage	Informed
Press Response:	Waiting for statement
Report Sheet Issued By:	
Name:	FELICIA HONG
Title:	MARINE ADMINISTRATOR
Contact Details:	97773875





All Emails are to be sent to the following address: globalerc@ivs-services.com

IMO number	9838515
Date / Time of call from vessel:	18 Dec 2024 / 1509hrs Singapore time
Who contacted the Office:	Master Capt. Nguyen Dinh Khanh
Description of Incident:	Fire and explosion in E/R, crank case explosion is suspected
 Location of incident on board: 	E/R
 Any injuries / casualties: 	C/E Nguyen Van Dung - Burn injury, Unconscientious 4/E Nguyen Cong Anh - hand and leg injury, concussion They are in process of being evacuated
Damages:	No damage yet
Date / Time of incident on board:	Not yet known, Master was quite busy in dealing the situation
Ship's position:	26 - 00N, 066-37E, vessel drifting in the Iranian water
Course	
• Speed	
 Cargo On-board and quantity: 	58071 MT
Bunker quantity on board:	Not yet known
Any Oil Spill:	No
 Approx Quantity spilt over board: 	Nil
 Next Port and distance 	New Orleans
Weather conditions:	

Reminder: Master/Office to follow the relevant contingency plan

Kind Regards
Capt. Rajesh Sharma
DPACSO
TAMAR
SHE MANACEMENT Hong Kong
1 Ternasek Avenue, 10-02 Milenia Tower, 039192, Singapore
DICK +66 6962 1393 | Mcbile-66 9777 8773
Email: RajeshS@vs-services.com
For and on behalf of Owners as Agents only



From: Ashish Kambo <AshishK@ivs-services.com>
Sent: Wednesday, December 18, 2024 3:34 PM

Cc: GSH Global Emergencies <globalerc@ivs-services.com>; globalerc@grindrobshipping.com; IVS Services - Crewing <crewing@ivs-services.com>

Subject: Exercise IVS Dunes - Drill, Drill, Drill

THIS IS DRILL ++++ THIS IS DRILL+++ THIS IS DRILL

Dear Local Agent/WSS,

As the technical managers of IVS Dunes, we have received a distress call from the vessel currently adrift in Omani waters at GPS position XXXXXX, XXXXXE, following an explosion in the engine room.

Two crew members have been injured:

Chief Engineer Nguyen Van Dung – unconscious.

4th Engineer Nguyen Cong Anh – conscious but requiring urgent medical attention.

The Master has contacted MRCC, and a helicopter is being dispatched to medevac the injured crew from the vessel.

We urgently request your coordination and assistance in arranging the following:

- 1. Transport the injured crew members to the emergency ward of a hospital.
- 2. Make all necessary arrangements to ensure they receive prompt medical attention.
- 2

Please confirm your receipt of this email and provide an update on the arrangements.

Thank you for your immediate support in this critical matter.Best regards,

Captain Ashish Kambo Head of Crewing

ISLAND VIEW
SHIPPING SERVICES
For and on behalf of Owners as Agents only.

Island View Shipping Services
1 Temasek Avenue | I #10-02 Millenia Tower



From: Jaja Casas <jajac@ivs-services.com>
Sent: Wednesday, December 18, 2024 3:38 PM
Cc: GSH Global Emergencies <globalerc@ivs-services.com>; globalerc@grindrobshipping.com; IV5 Services - Crewing <crewing@ivs-services.com>
Subject: FW: Exercise IV5 Dunes - Drill, Drill, Drill

EXERCISE IVS Dunes

Dear PTC Team,

As the technical managers of IVS Dunes, we have received a distress call from the vessel currently adrift in Omani waters at GPS position XXXXXXX, XXXXXXE, following an explosion in the engine room.

Two crew members have been injured:

Chief Engineer Nguyen Van Dung – unconscious.

4th Engineer Nguyen Cong Anh – conscious but requiring urgent medical attention.

The Master has contacted MRCC, and a helicopter is being dispatched to medevac the injured crew from the vessel.

We urgently request your coordination and assistance in arranging the following:

- 1. Transport the injured crew members to the emergency ward of a hospital.
- Make all necessary arrangements to ensure they receive prompt medical attention.
- 3.

Please confirm your receipt of this email and provide an update on the arrangements.

Thank you for your immediate support in this critical matter

EXERCISE IVS DUNES

Kind Regards,

Jaja

Jaja D. Casas

Crew Manager

ISLAND VIEW
SHIPPING SERVICES
For and on behalf of Owners as Agents only.



To: edward.bennett@ambrey.com; fleur.brewer@ambrey.com
Cc: exercise1@noreclub.no; GSH Global Emergencies <globalerc@ivs-services.com>
Subject: Exercise fVS Dunes Exercise

Gents

Please find attached the sitrep – Our vessel is incapacitated due to an Engine Room Crankcase explosion. We will add you to our WhatsApp group for communication purposes.

Vessel is positioned: 26 - 00N, 056-37E, vessel drifting in the Iranian water



FOLLOW UP SITUATION REPORT

Ship Name:	IV8 Dunes
SITREP No:	01
Date and Time (UTC) of situation report	18 Dec 2024 / 1517hrs
Summary / Update of the incident	
Update of the incident	Fire and explosion in the engine room, Suspected fire started from Crank Case. No External Damage to the ship hull at this point of time. Crews are busy evacuating.
Information received from:	Master of IVS Gleneagles - Captain Ely Canaria
Number/Details of Casualties:	C/E Nguyen Van Dung he is unconscious and 4/Eng Nguyen Cong Anh Hand and Leg Injury concussion
Damage:	Hull not reported damaged
Any external assistance required:	Helivac expected about 15 minutes, both injured officers to be sent to soher oman hospital.
Authorities Involved:	Flag state and port state
Emergency Services Involved:	MRCC
Response Services Involved:	Medivac using helicopter
Company Emergency Response Activities:	ERC activated
Press Media Coverage	Navigate Response informed
Press Response:	NIL
Report Sheet Issued By:	
Name:	RAJESH SHARMA
Title:	DPA
Contact Details:	97778773

Kind Regards,

Brett



From: Ning Wu <NingW@hrs-services.com>
Sent: Wednesday, December 18, 2024 3:50 PM
Cc: GSH Global Emergencies rglobalerc@ivs-services.com>
Subject: Exercise IVS Dunes - Drill, Drill, Drill

EXERCISE IVS DUNES

Dear MRCC

As the technical managers of IVS Dunes, we have received a distress call from the vessel currently adrift in Omani waters at GPS position 26 - 00N, 056-37E,

following an explosion in the engine room.

Two crew members have been injured:

Chief Engineer Nguyen Van Dung – unconscious. 4th Engineer Nguyen Cong Anh – conscious but requiring urgent medical attention.

The Master has contacted MRCC, and a helicopter is being dispatched to medevac the injured crew from the vessel.

FOLLOW UP SITUATION REPORT

Ship Name:	IVS DUNES
SITREP No:	01
Date and Time (UTC) of situation report	18 Dec 2024 / 1517hrs
Summary / Update of the incident	
Update of the incident	Fire and explosion in the engine room, Suspected fire started from Crank Case.
	No External Damage to the ship hull at this point of time. Crews are busy evacuating.
Information received from:	Master of IVS DUNES - Captain Nguyen Dinh Khanh
Number/Details of Casualties:	G/E Nguyen Van Dung he is unconscious and 4/Eng Nguyen Cong Anh Hand and Leg Injury concussion
Damage:	Hull not reported damaged
Any external assistance required:	Hetivac expected about 15 minutes, both injured officers to be sent to sohar oman hospital
Authorities Involved:	Flag state and port state
Emergency Services Involved:	MRCC
Response Services Involved:	Medivac using helicopter
Company Emergency Response Activities:	ERC activated
Press Media Coverage	Navigate Response informed
Press Response:	NIL
Report Sheet Issued By:	
Name:	RAJESH SHARMA
Title:	DPA
Contact Details:	97778773

EXERCISE IVS DUNES

Best Regards

Captain WU NING



From: Ning Wu-chingWights-services.com> Sent: Wednesday, December 18, 2014, 3:58 PM Cc: GSH Global Emergencies -globalero@liss-services.com> Subject: Esercise IVS Durses - Drill, Drill, Drill

EXERCISE IVS DUNES

Doar NHC Emergency Phone (For Notification Only)

As the technical managers of IVS Dunes, we have received a distress call from the vessel currently adrit in Omani waters at GPS position 26 - 00N, 096-37E,

following an explosion in the engine room.

Two crow members have been injured:

Chief Engineer Nguyen Van Dung – unconscious. 4th Engineer Nguyen Cong Anh – conscious but requiring urgent medical attention.

The Master has contacted MRCC, and a helicopter is being dispatched to medicial the injured crew from the vessel.

FOLLOW UP SITUATION REPORT

Ship Name:	IVS GLENEAGLES
SITREP No:	01
Date and Time (UTC) of situation report	26 Nov 2024 / 1517hm
Summary / Update of the incident	
Update of the incident	Fire and authoritor in the engine room, Suspected fire started from Grank Case. No Esternal Damage to the ship bull at this point of time. Crews are busy execusting.
Information received from:	Maxter of IVS Gleneagles: - Capitain Bly Canaria
Number/Details of Casualties:	C/E lake he is unconscious and 4/Eng Nguyen Gong Anh Hand and Leg Injury concussion
- Damage:	Hull not reported damaged
Any external assistance required:	Helivac expected about 15 minutes, both injured officers to be sent to sohar own hospital
Authorities Involved:	Flag state and port state
Emergency Services Involved:	MRCC
Response Services Involved:	Mechanic uning helicopter
Company Emergency Response Activities:	ERC activated
Press Media Coverage	Navigate Response informed
Press Response:	NIL
Report Sheet Issued By:	
Name:	RAJESH SHARMA
Title:	DPA.
Contact Details:	97778773

EXERCISE IVS DUNES

Bost Regards

Captain WU NING Narins & Training Superintendent ISM/ISPS Internal Auditor & MLC Internal Inspector For and on behalf of Owners as Agents only.

ISLAND VIEW

SHIPPING SERVICES

Island View Shipping Services / Tamer Ship Management

1 Terrisasis Avenue #10-02 Millenia Tower Bingapore 039/192

SGP LT-UTC + 8 HRS





DRILL_draft_media statement_IVS Dunes_18 Dec 2024_1554hrs.docx

From: Casey Chua < Casey.Chua@navigateresponse.com

Sent: Wednesday, December 18, 2024 3:58 PM
To: Hilton Stroebel < hiltons@ivs-services.com >

Cc: Navigate_Operations <<u>Operations@navigateresponse.com</u>>; Mads Walther <<u>MadsW@ivs-services.com</u>>; <u>exercise1@norclub.no</u>; GSH Global Emergencies <<u>globalerc@ivs-services.com</u>>; Jaja Casas <<u>jajac@ivs-services.com</u>>; Ashish Kambo <<u>AshishK@ivs-services.com</u>>

Subject: Re: Exercise IVS Dunes - Drill, Drill, Drill

THIS IS A DRILL...THIS IS A DRILL...THIS IS A DRILL...

Dear Capt Hilton

I have amended the draft holding statement (see attached) based on the latest sitrep. For your review, please.

Regards

Casey

Casey CHUA (Mr) | 蔡嘉全

Crisis Communications Director

Navigate Response

23B Teo Hong Road

Singapore 088332

T: +65 6222 6375

M: +65 9878 3007





THIS IS A DRILL... THIS IS A DRILL... THIS IS A DRILL...

DRAFT

18 December 2024

Media Statement

Tamar Ship Management Pte. Ltd. has launched an emergency response following an incident involving a fire on board its managed bulk carrier *IVS DUNES* (IMO: 9838515).

The incident occurred at about 15:09 Singapore time (UTC+8) on 18 December 2024 in the Strait of Hormuz during the vessel's laden passage from the Port of Mesaieed, Qatar to New Orleans, USA.

The crew are carrying emergency firefighting to bring the situation under control.

Two crew members who sustained injuries during the incident are being medically evacuated to the nearest hospital.

There are no reports of pollution thus far.

Tamar has notified the local authorities and relevant parties. Its priorities are to ensure the safety of the crew, mitigate possible pollution to the marine environment, and to ensure the safety of the vessel.

More information will be provided when it becomes available.

- ENDS -

For media enquiries, please call Navigate Response on +65 6222 6375 / +44 20 7283 9915 or email operations@navigateresponse.com



From: Yogesh Devendra Negi < Yogesh N@ivs-services.com>
Sent: Wednesday, December 18, 2024 4:01 PM
Cc: GSH Global Emergencies < globalerc@ivs-services.com>; globalerc@grindrodshiping.com
Subject: Exercise IVS Dunes - Drill, Drill, Drill

EXERCISE IVS DUNES

Dear Sirs (Duqm SHIPYARD, Oman) Good Day

We would like to enquire for URGENT docking space for our vessel IVS Dunes, (IMO No: 9838515)

She is currently adrift in Omani Water at GPS position 26 - 00N, 058-37E and would require assistance in towing to your ship yard.

Please note she is 58000 Tonne DWT & 185.50 mtr LOA.

Kindly check and revert Urgently with confirmation if any free space for our vessel.

EXERCISE IVS DUNES

Best Regards, YOGESH NEGI Technical Superintendent

SHIPPING SERVICES
For and on behalf of Owners as Agents only

Island View Shipping Services 1 Temasek Avenue #10-02 Millenia Tower Singapore 039192 Mob No : +65 88587985

E-mail: YogeshN@ivs-services.com



From: Brett McElligott <BrettM@ivs-services.com>

Sent: Wednesday, December 18, 2024 4:47 PM

To: Felicia Hong <FeliciaH@ivs-services.com>; GSH Global Emergencies <globalerc@ivs-services.com>; Ambrey Guardian <guardian@ambrey.com> Cc: EXERCISE1@norclub.no

Subject: RE: EXERCISE IVS DUNES - SITREP SIX

Adding you in on the Sitreps onboard the vessel

Please advise ETA of US Destroyer, US Helicopter and any other helicopters for evacuation....

Kind Regards,

Brett

Brett McElligott SHEQ Manager

ISLAND VIEW
SHIPPING SERVICES
For and on behalf of Owners as Agents only.

Island View Shipping Services Office 3A, 3rd Floor, The Boulevard, 19 Park Lane, Parkside, Umhlanga 4319, South Africa P O Box 3483, Durban, 4000, South Africa

≅: +27 (0)31 302 7964 | **1**: +27 (0)82 314 9983 ☑ <u>brettm@grindrodshipping.com</u>



From: Ambrey Guardian guardian@ambrey.com>
Sent: Wednesday, December 18, 2024 4:57 PM
To: Rajesh Sharma <RajeshS@ivs-services.com>
Cc: GSH Global Emergencies <globalerc@ivs-services.com>; exercise1 <exercise1@norclub.com>
Subject: RE: EXERCISE IVS DUNES Exercise URGENT

Good day

A phone call has just been had between Ambrey and Brett McElliot – the ETA of tugs to assist is unrealistic and will likely be refused by Iranians. This may escalate the situation.

ETA of Navy Helicopter is 10 mins however there are NO EVAC capabilities. ETA of Destroyer USS MASON is 3 hours.

Kind regards,
Fleur Brewer

Maritime Operations Officer

24/7 +44 (0)20 3503 0320

E fleur.brewer@ambrey.com | W www.ambrey.com



This e-mail (including all attachments) is intended for the named addressee(s) only. It may contain confidential and privileged information. Any unauthorised review, use, copying, distribution and/or disclosure is prohibited. If you are not the intended recipient, please notify the sender immediately and delete this message from your e-mail system. Although this message has been scanned for viruses, we make no representation or warranty as to the absence of viruses in this email (including all attachments).



From: Brett McElligott <BrettM@ivs-services.com>
Sent: Wednesday, December 18, 2024 5:03 PM
To: Ambrey Guardian <guardian@ambrey.com>; Rajesh Sharma <RajeshS@ivs-services.com>
Cc: GSH Global Emergencies <globalerc@ivs-services.com>; exercise1 <exercise1@norclub.com>
Subject: RE: EXERCISE IVS DUNES Exercise URGENT

Hi Ambrey

THE DRILL IS OVER AND COMPLETE.

Many thanks for your input. If during your washup you note any issues we could have done better – please advise...

Kind Regards,

Brett

Brett McElligott SHEQ Manager



Island View Shipping Services
Office 3A, 3" Floor, The Boulevard,
19 Park Lane, Parkside,
Umhlangs 4319, South Africa
P O Box 3483, Durban, 4000, South Africa

☎: +27 (0)31 302 7964 | 1: +27 (0)82 314 9983

☑ brettm@grindrodshipping.com



Appendix C - Shipboard drill report (Not Applicable as Simulated by NHC)

	HEALTH, SAFETY, ENVIRONMENT AND CUMITY MANUSCRIENT SYSTEM	Form: 525 Page 1 ol 2
	EMERGENCY DRILL AND TRAINING REPORT	Date : 01-Feb-34 Rev : 100
Server Sect remodel to all	REPORTING FORMS MAINLAS.	App By: BMM

Ship's Name:	-MS DOMES
Date / Time :	±012/9024
Location :	1 Sino
Westher:	DODERATE SEA, MODERATE SWELL, GOOD VISI, FRESH BREEZE

Note:

- Include all trainings and drills conducted on board in this report.
- For reflective learning and learning engagement tools include Location, Facilitator, Number of attendeds, Team action and Management follow up in Record of events section.

Bnil/Insining Type

EXPLOSION IN ENGINE ROOM AND FIRE DRILL (Crank case explosion)

Record of Events:

2004.T: General starm sounded and followed by master announced on public address system. Simulated explosion and fire in engine room, assemble of over-

15821.T: Drew proceed to muster station preparing for the duties described in the muster list.

1593LT: Reparted CE and 4th Engineer injured and location of explosion crank case explosion, tust remote control values activate, and closed Emergency team and emergency ten pump standity. After explosion, there is are all fire at 2nd floor Engine room.

1594LT: Checked fremen's outilitiest other equipment required alp Muster list, communication equipment in good condition.

1504LT: Master ordered shutdows all vertilation fan and door of the fire area, switch off elect power to fire point, standby EMG fire pump, fire house.

1585LT: DE report EB6G Fire gump rendy and started followed Master Order, Verdission of relative areas were

shuidown, 2 fine boson jets of water in high pressure show that emergency fine pump worked in good order.

1596LT: Firefighter donned firemen cutfit, pressure shecked, low pressure alare tested ok, radio for firefighter checked and tested ok reported to Master by CIO.

1586LT: Finemen's proceed to fine area and combating the fire followed Master order.

1514LT: CIO reported to Master The fire is under control by fire hoses. Fire extinguished.

1515LT: Master gave instruction to re-checking fire spot condition after 5 minutes and the high pressures was water keep cooling of the time.

15/8LT: CIO reported: the temperature low down & Fireman detected fire no possibility of re-igniting. 1529LT: Master ordered: Fire Onli Finished.

Debreiting (Cvst.usion Feedback/Suggestions for improvement/dentification of training needs etc):

all participants understood well. Liederstand how to must their series of emergencies as per emergency contingency

To ensure the safety of the vessel's crew and all other workers. The entire operation is to be performed ensuring any houseds are identified and the correct procedures are followed. A Drill is the process of practicing an existing contingency plan , during which the easigned specific during of each and individual sea terer see being practiced and an examination of what has been learned and studied and what can be improved.

Completion of Training (Fidentified during debrining):





HEALTH, SAFETY, ENVIRONMENT AND QUALITY MANAGEMENT SYSTEM

EMERGENCY DRILL AND TRAINING REPORT

REPORTING FORMS MANUAL

Form: 3.2.3 Page 2 of 2 Date: 01-Feb-24 Rev: 10.0 App By: BMM



NGUYEN DINH KHANH


Master's Name/Signature

VU XUAN HIEU

Deck Officer's Name/Signature









Exercise Scenario

1. Setting:

IVS DUNES is enroute fully laden from Mesaieed Port in Qatar to New Orleans in US.

POB: 21 (See Crew/NoK list)

2. Incident:

Explosion + Fire in the engine room. Black Out. The vessel is drifting towards Iranian waters.

Injured persons in the fire:

- Chief Engineer, Nguyen Van Dung (Burn Injuries, Unconscious)
- Fourth Engineer, Nguyen Cong Anh (Burn injuries, Head and leg injuries due to fall, Conscious)


3. Development

Drifting towards shallow waters. Development of scenario iaw. Captains decision and in coordination with MRCC, simulated by NHC.

Optional development:

- Medevac of injured persons to New Khasab Hospital in Oman... Is this a relevant and approved Hospital?
- JRCC Masqat Oman involved but MRCC Bandar Abbas is also eager and wants to take over operation
- Leaking Oi
- Naval vessels from both Iran and EU Operation Aspides in area. IVS Dunes is forced to abandon ship. Reluctant to do so...What to do?
- Iranian Forces to intervene. Threatening to take over IVS Dunes

Exercise Scenario





FIRE IN ENGINE ROOM (If vessel in port - see 14)

18

ACTION (NOT NECESSARILY IN ORDER)
Sound the general alarm. Muster crew and passengers and determine all accounted for.
Attack the fire with appropriate fire extinguishers, but only if there is more than one person present.
If the fire cannot be brought under control swiftly the engine room must be evacuated without delay. The fixed water mist installation, if fitted, should be activated at this time. (Can be done while E/R still manned.)
Alter course away from navigation hazards and if possible, onto a heading that will assist to reduce the spread of flames.
Seal engine room and shut off ventilation once the space is confirmed unoccupied.
Activate the fixed CO2 firefighting installation if the water mist system has not extinguished the fire or is not fitted. If it is inoperative then keep the engine room sealed. The fire will eventually starve provided the engine room remains intact and no air gets in.
Activate fuel trips to shut off fuel tanks.
Broadcast an URGENCY message and advise the Company and charterers, if applicable.
Seal all cargo holds.
Start the emergency fire pump.
Deck plating and superstructure in the vicinity of the engine room should be cooled with water spray. Check all bulkheads adjacent to the engine room and apply boundary cooling as necessary.
If the engine room cannot be sealed, then a spray of water or foam should be injected through the opening using clamped hoses.
The Emergency Party wearing SCBA should check the engine room to ensure that the fire is out, and all hot surfaces cooled, as even after a fire is thought to be extinguished, the danger of reignition is not over until all hot surfaces have cooled. Only when this is done, and not before, should the ventilation be started, and the space opened.



FIRE IN ENGINE ROOM (If vessel in port - see 14)

18

	CONTINGENCY PLAN FOR FIRE IN THE GALLEY
1.	The majority of engine room fires are caused by fuel or oil igniting when sprayed under pressure onto a hot surface such as an exhaust. Poor housekeeping together with hotwork or spontaneous combustion of oil-soaked rags are another cause. Crankcase explosions are known to have caused major engine room fires when fuel from damaged fuel lines ignited on a hot exhaust. Due to the large concentration of electrical machinery and equipment in the engine room an electrical fire is another possibility.
2.	Good housekeeping is essential, and bilges must be kept clean and dry. Leaks must be attended to immediately and lagging kept free of oil. Fuel injection pipes should be double wall sheathed and equipment/exhausts in the vicinity of fuel, diesel, high pressure hydraulic and lubricating oil pipes should be protected against spray.
3.	Rapid intervention with appropriate portable fire extinguishers will in most instances extinguish a small fire in the engine room before it has the opportunity to do damage, but -: NEVER FIGHT A FIRE BEFORE RAISING THE ALARM!! and
	NEVER ATTEMPT TO FIRE THE FIRE ON YOUR OWN!!
4.	Oil-soaked lagging is liable to re-ignite when it comes in contact with fresh air if it is not cooled sufficiently.
5.	If the fire cannot be controlled with portable fire extinguishers, it should be fought by using the fixed firefighting installation. If the fixed water mist system (if fitted) is not automatically released, it should be activated as soon as possible, as it may be used while personnel are still in the E/R, and with essential machinery still running. The fixed CO2 system should be used as a last resort – but with as little delay as possible once it is determined that other methods have not been successful. It is essential to ensure that the E/R is properly sealed and remains so until the fire is extinguished.
6.	If the fixed firefighting system is inoperative and using hoses cannot control the fire, the space should be sealed, and all ventilation shut off. The fire should go out eventually provided that the engine room remains intact, and no air gets in.
7.	If the engine room cannot be sealed, then a spray of water or foam should be injected through the opening.
8.	The emergency fire pump will have to be utilised. The emergency generator should be run to supply power but the power supply to the engine room should be isolated.
9.	Take care to ensure that all accessible spaces adjoining the engine room are checked for heat build-up, and that boundary cooling is applied as necessary.
10.	Allow plenty of time before attempting to re-enter the engine room because the danger of re-ignition is not over until all hot surfaces have cooled. Two Emergency Party team members wearing appropriate PPE, SCBA and safety lines should first check the engine room. When making entry try and minimise the amount of air entering the space.
11.	Only when the engine room is declared free of hot surfaces may the ventilation be started, and the space opened. Ventilate the space thoroughly to remove toxic fumes and smoke. The oxygen content is especially important after smothering gas has been used to fight a fire. Ensure enclosed space entry procedures are followed before allowing unrestricted entry.



STRUCTURAL FAILURE / ASSESSMENT OF HULL 34 **DAMAGE**

ACTION (NOT NECESSARILY IN ORDER)
Sound general alarm, assemble crew and activate emergency contingency plan.
Investigate where structure has failed and is there any ingress of water in any tank or compartment.
In circumstances deemed justifiable for sending personnel onto decks that may be frequently awash with green water, at least two personnel should go to investigate. They should wear harnesses that attach them to a lifeline and to each other and should be in constant (radio) communication with the bridge.
Inform the company of the incident and related information with master's view and comments.
Whether voyage can continue or urgent repair is needed on way to destination port
Handle the ship carefully so that the failure may not spread. Consider Slowing down, changing course, de-ballasting, etc.
Check all emergency systems are ready for immediate use
Check bilge & ballast pumps are lined up ready for immediate use.
Refer loading manual/computer in relation with bending moment and shearing force and damage stability.
Activate Damage Assessment for stability through office. Send vessel's load condition to office.
Prepare life-saving equipment for evacuation if sustained damage is identified or suspected. However, abandonment by spoken orders of the master following assessment of the risk.
Contact with a Maritime Rescue Co-ordination Centre (MRCC) in case of any suspicion that the ship is damaged.
Send an URGENCY signal and upgrade to DISTRESS if the ship is confirmed as damaged.
When a loss of hull integrity is known or suspected, personnel should not be sent onto decks that are being regularly submerged or deeply awash.
When a loss of hull integrity is known and ship is in imminent danger, activate ABONDON SHIP contingency.





STRUCTURAL FAILURE / ASSESSMENT OF HULL DAMAGE

34

STRUCTURAL FAILURE

The structure failure may be caused due to sloshing/cargo movement damage to bulkhead or slamming damage to forward bottom. Routine sounding of tanks and void spaces and development of sudden list or trim do give an indication of structural failure.

Heavy cargo: Heavy cargo such as iron ore, steel product leave large unoccupied space in the cargo holds. In case of flooding, the large volume of water entered in cargo hold rapidly destroy the ship's residual buoyancy, its stability and makes vessel susceptible to structural failure due to increase of weights caused by the influx of water. Heavy cargoes place high loads on the structure, and structural failure is therefore more probable when subjected to the additional forces associated with flooding.

IMSBC Code Group A Cargo: When vessel is loaded with IMSBC Code Group A cargoes which are liable to liquefaction due to moisture, if the moisture content in the cargo is more than its TML or any ingress of water in the hold will turn such cargo rapidly in the liquid form, making vessel more susceptible to structural failure due to sloshing effect of liquid cargo and loss of GM due to free surface effect.

Structure: Deterioration of structure through corrosion, fatigue and damage is identified as a principal factor in the loss of many bulk carriers. Failing to identify such deterioration may lead to sudden and unexpected failure.

Forward flooding: Spaces forward of the collision bulkhead will, in the event of flooding, significantly affect the trim of the ship and reduce freeboard at the bow. In extreme weather condition, ship's ability to resist further escalation of flooding is compromised.

Early assessment: Master should quickly assess damage to their ships by being alert to water ingress and its consequences. The following quidelines are given to assist them in this assessment.

- · Unusual motion or attitude of the vessel
- · An unusual trim or heel
- Sudden changes of heel or trim will indicate flooding or in smaller ships with lighter cargoes it may indicate cargo shift.
- · Jerky lateral motions can be indicative of large-scale sloshing as would be the case if a hold were flooded.
- Slowing of the ship's roll period may indicate excessive water within the hull a serious threat to stability.
- Increases of water boarding forward decks may indicate flooding of a forward compartment. Trim and freeboard changes are notoriously difficult to assess from an after bridge.

Methods of detection:

- . Hatch covers may be dislodged by pressure and/or sloshing from within a hold if
- flooding occurs through side shell or bulkhead.
- Sudden pressurization of compartments adjoining those that are damaged or flooded will indicate failure of internal subdivision, most notably bulkheads.
- · Spaces may be monitored, either using gauging or bilge/water level alarms.
- Visual monitoring from the bridge using binoculars.
- · Assessment of trim changes can in certain conditions be detected by noting the level of
- the horizon, when visible, against a known reference point on the foremast.
- Draught and trim can be assessed using draught gauges.

Investigation: Masters may wish to investigate any suspected water ingress more closely but preparations for evacuating the ship should be made WITHOUT DELAY and concurrent with any investigation. Remote methods of observation are preferable to sending personnel onto decks, particularly in bad weather and/or at night. Deck floodlights should be used if necessary to try and identify abnormalities. Detrimental effects on watchkeepers' night vision are of secondary importance in such circumstances.

Reference: MSC/Circ.1143





HELICOPTER EMERGENCY

30

ACTION (NOT NECESSARILY IN ORDER)
Sound the general emergency alarm
Muster all crew, take head count, explain the emergency situation to all crew and the action plan
Inform engine room / Keep M/E on 'standby'
Fix ship's position
Alter course and speed as required to keep fire and smoke clear of deck
Initiate emergency procedures for the situation prevailing
Send "Urgency / Distress" message as applicable & inform all ships in vicinity
Establish Communication (Using portable VHF transceivers or other means)
Isolate all power to the area in the vicinity of incident
Make analysis of situation; consider priority of measures
Initiate external response if required
Ensure crew safety. Evacuate crew from helicopter as soon as possible
If possible switch off power on helicopter
Confirm readiness of Fire Main water, Fixed Fire-fighting appliances etc
Start fire pumps
Keep first aid kit , stretcher, blankets etc in readiness
Announce 'All-clear' so that the crew may safely emerge to attend to personnel rescue and firefighting operations
When ordered by command team, approach helicopter wearing protective clothing to effect rescue, using axe, wire cutters and crow bar etc as necessary
If fire is small consider use of extinguishers for fire fighting
Provide water spray or foam as applicable. Contain and extinguish the fire/explosion, if any
Keep survival crafts ready for launching if required
When fire is extinguished and crew rescued, investigate damage and check re-ignition risk
Evacuate injured to a safe & comfortable location
Assess damage to ships structure
Make notifications to relevant parties

References:

- · Guide to helicopter/ ship operations
- IAMSAR





SERIOUS INJURY / ILLNESS

31

	ACTION (NOT NECESSARILY IN ORDER)
Α.	Initial Actions
	Sound emergency alarm and muster all crew
	Make the area around the injured person safe to prevent further injuries
	If there is a risk of internal injury do not move the injured person until experienced medical person is present or radio medical advice is received
	Bring relevant equipment (first aid kit, stretcher, resuscitator, splints etc.)
	Arrange the injured in a stable side position and keep him/her warm
	Administer "first aid": a. Airway kept clear b. Breathing and heartbeat ensured (otherwise Cardio Pulmonary Resuscitation required) c. Bleeding controlled (casualty not to be moved unless imperative)
	Call port authorities for Ambulance if in port. Establish communication and transport casualty to hospital if possible
	Consider medical evacuation (medivac) if required by consulting with relevant authorities
	Inform company for seeking medical advise
В.	Subsequent Actions
	Complete the form 4.1.9 (a: IN THE CASE OF ILLNESS) or form 4.1.9 (b: IN THE CASE OF INJURY) before calling for assistance, except in emergencies
	Contact "Dr Dungan" or "CIRM ROME" or "The Royal Netherlands Sea Rescue Organization- Radio Medical Service" or other medical professionals for radio medical advice as per Admiralty List of radio Signals Vol.1
	Since the doctor may not be aware of the contents of your ship's medical chest, have ready a complete list of the drugs and appliances available on board.
	Monitor and record patient's condition and update to applicable medical service
	Keep the injured warm
	Protect casualty from further injury and shock





SERIOUS INJURY / ILLNESS

31

	Do not take minor injuries lightly, examine the casualty further for
	Unconsciousness
	b. Suspected internal bleeding
	c. Stab or puncture wounds
	d. Wounds near joints (see fractures)
	e. Possible fractures
	f. Eye injuries
	Prepare for evacuation if necessary
\vdash	Inform nearest Maritime rescue co-ordination centre (MRCC) / AMVER - who will contact shipping
	and other sources of assistance in the vicinity
	Arrange for launch / helicopter if medical evacuation is required
	Threating for manifest threating of addition to require
	Consider deviating to nearest port after discussion with company
	Monitor patient condition continuously
	Should the crew member require further treatment in a hospital a Medical treatment form 4.1.8A
	is to be filled in by the Doctor providing treatment

Note:

- Company will inform P&I Club
- If the illness/injury is very serious requiring hospitalisation then the vessel's Flag is to be informed using relevant Form as required by flag state.
- The following doctors are available on a 24/7 basis:

For ships on the South African Coast and or for ships trading internationally:

Shipmed (contact details as per Section 1: Communications in the Emergency Procedure Manual

OR

If Shipmed is not available:

The Royal Netherlands Sea Rescue Organization
Radio Medical Service
Phone: +31 223 54 2500
INMARSAT- telex and email:
(Urgent MEDEVAC) 38@rmd.knrm.nl
(Regular MEDICAL) 32@rmd.knrm.nl
(Non-Urgent) 00@rmd.knrm.nl,
e-mails are automatically relayed to the doctor in charge

OR

INTERNATIONAL RADIO MEDICAL CENTRE (C.I.R.M.)

Phone: +39-06-59290263 E-Mail: telesoccorso@cirm.it

Reference materials: International medical guide. MFAG, ALRS VOL 1 IAMSAR

