

## SAFETY, HEALTH, ENVIRONMENT AND QUALITY MANAGEMENT SYSTEM

## PORT OF CALL HISTORY

## REPORTING FORMS MANUAL

Form: 1.3.1B Date: 02/June/2017 Rev: 1.0 App By: BMM

## Port Feedback

Ship Name	IVS WENTWORTH
Port	MUARA PANTAI, INDONESIA
Terminal & Berth No.	MUARA PANTAI ANCHORAGE, INDONESIA

Port Details	
Anchorage approach	Vessels anchor in depth 32.0–36.0 m.
Min. depth at anchorage/Channel	18.04m
Pilot performance/Tugs condition	N/A
Other information	Offshore coal transshipment/anchorage area. Mined coal is transported by barge from one of three shore terminals to the transshipment/anchorage area for loading onto seagoing geared and gearless bulk carriers.

Berth Details	
Berth Type	Anchorage
Minimum depth at Berth/approach/UKC concern	0.48m
Mooring arrangement	NIL
Berth Restrictions	NIL
Berth condition/fendering etc	NIL
Other information (fendering etc)	NIL

Cargo Operation		
Manifold connections	NIL	
Terminal courtsey/co-operation	NIL	
Safety standard	NIL	
Other information (booster pumps etc)	NIL	

Additional information	
Authorities(Custom/immig./health)	Satisfactory
Security (Stowaways/theft threats)	Appropriate security watches deployed on deck
Spares/Stores/FW supply	No stores/spares and FW received.
Crew change/Shore leave	Crew change carrier out. 3 signed off and 5 signed on
General comments	Cargo operation depends on the availability of barges coming in and out of the river to wait for favourable tide.
	Engure vessel has sufficient fonders to provent caratches caused by
Recommendations	Ensure vessel has sufficient fenders to prevent scratches caused by cargo barges.

Master's Name / Date	Capt. Krzysztof Z. Senczuk