

Crew change/Shore leave

General comments

Recommendations

Master's Name / Date

SAFETY, HEALTH, ENVIRONMENT AND QUALITY MANAGEMENT SYSTEM

PORT OF CALL HISTORY

## REPORTING FORMS MANUAL

Form : 1.3.1B Date : 02/June/2017 Rev : 1.0 App By : BMM

Port Feedback	
Ship Name	IVS Swinley Forest
Port	Beira, Mozambique
Terminal & Berth No.	Berth 08
Port Details	
Anchorage approach	6.0nm SE Bouy A
Min. depth at anchorage/Channel	13m anchorage / 8m in channel
Pilot performance/Tugs condition	Satisfactory / Good
Other information	Shore gangway used in Berth 08
Berth Details	
Berth Type	Concreted quay
Minimum depth at Berth/approach/UKC concern	8.0m at channel / UKC to be monitored regularly
Mooring arrangement	4 + 2 Fwd & Aft
Berth Restrictions	10m maximum draft
Berth condition/fendering etc	Poor, old tires used as fenders. Bollards are of irregular sizes
Other information (fendering etc)	Satisfactory
Cargo Operation	
Manifold connections	N/A
Terminal courtsey/co-operation	Satisfactory
Safety standard	Satisfactory / As per port advice
Other information (booster pumps etc)	2 shore loader available (conveyor belt)
Additional information	
Authorities(Custom/immig./health)	10 Dec. 2020
Security (Stowaways/theft threats)	A watchman is provided
Spares/Stores/FW supply	NIL

NIL

constantly subject to silting

Safely berthed. Monitor UKC even at berth as bottom is

Capt. Miroslaw Boguslaw Kaczmarczyk / 12 December 2020