

## SAFETY, HEALTH, ENVIRONMENT AND QUALITY MANAGEMENT SYSTEM

## PORT OF CALL HISTORY

## REPORTING FORMS MANUAL

Form: 1.3.1B Date: 02/June/2017 Rev: 1.0 App By: BMM

## Port Feedback

Ship Name	IVS GLENEAGLES
Port	RICHARDS BAY, SOUTH AFRICA
Terminal & Berth No.	BERTH NO. 702

Port Details	
Anchorage approach	Suggested anchorage is 3-5nm SE of the South Breakwater, sandy bottom. Caution should be exercised in high SW and NE winds. The anchorage area immediately to the N of the entrance channel is prohibited due to the location of an offshore pipeline.
Min. depth at anchorage/Channel	An inner breakwater, exhibiting a light, extends approx 70m S and SSE from the N entrance point.  Within the harbour entrance, which is marked by lightbuoys and dredged to 19.5m LWOST over a width of 300m, the harbour opens into a basin dredged to 19.0m and containing a turning area with a diameter of 800m. Berth depths are dredged to 19.0m LWOST.
Pilot performance/Tugs condition	Satisfactory / 2 good Tugs used
Other information	ZARCB / Ø 28-48S λ 032-03E

Berth Details	
Berth Type	Wharf
Minimum depth at Berth/approach/UKC concern	Berth Depth 18.90m / Harbour Channel depth 19.4m / sufficient UKC as per company policy
Mooring arrangement	F & A = 4+2
Berth Restrictions	Arrival ballast requirements:  Length Draught Fore Draught Aft Up to 250m 2% of length 3% of length Above 250m 2.5% of length 3.5% of length Any vessel unable to comply with ballast requirements should contact port control in advance of arrival.
Berth condition/fendering etc	Good / Satisfactory
Other information (fendering etc)	Nil

Cargo Operation		
Manifold connections	N/A	
Terminal courtsey/co-operation	Good	
Safety standard	Good	
Other information (booster pumps etc)	Nil	

Additional information	
Authorities(Custom/immig./health)	Authorities came on board but only in the Gangway & Tally Office outside accomodation due to COVID-19 (AGENT/CUSTOM/IMMIG/HEALTH)
Security (Stowaways/theft threats)	ISPS compliant / MARSEC Level 2
Spares/Stores/FW supply	Available via Agent & Ship's Chandler. Received Ship Stores
Crew change/Shore leave	Yes but temporarily banned due to COVID-19
General comments	Disch Port for Voy 2005, Cargo: Sulhpur in Bulk
	Movements of shore & ship staffs during cargo operations was very limited due to COVID-19
	Vsl bunkered lub oil
	No Stowaway or security issues during the port stay
Recommendations	Maintain safety & security watch at all times. Ensure COVID-19 on board preventive measures are strictly implemented

Master's Name / Date	CAPT. GEORGE SARMIENTO / 13 AUG 2020