

SAFETY, HEALTH, ENVIRONMENT AND QUALITY MANAGEMENT SYSTEM

PICTURE SUBMISSION FORM

Reporting Forms Manual

Form: 5.2.1D Page: Page 1 of 6 Date: 07 June 2018

Rev No. 1.2 Appr: BMM

VESSEL: DATE: Click or tap to enter a date.

AREA / LOCATION : LSA – POOR PRACTICES RESULTING IN PSC DEFICIENCIES/ DETENTION

41 (41 (



Damaged lifeboat side shell



Glass not clear - poor visibility



Broken seat belt



Damaged lifeboat seat



Wasted davit housing



Wasted davit winch



Wastage of fall block



Onload release seized due to excessive paint



Release cable bent





SAFETY, HEALTH, ENVIRONMENT AND QUALITY MANAGEMENT SYSTEM

PICTURE SUBMISSION FORM

Reporting Forms Manual

Form: 5.2.1D Page: Page 2 of 6 Date: 07 June 2018

Rev No. 1.2 Appr: BMM







Broken oars



Damaged lifebuoy









Lifebuoy marking faded



Deteriorated. reflective tape



Incorrect setting of safety interlocks



Interlock not in locked position



Expired radar reflector



Buoyant lines not of non- kinking type





l ▶



SAFETY, HEALTH, ENVIRONMENT AND QUALITY MANAGEMENT SYSTEM

PICTURE SUBMISSION FORM

Reporting Forms Manual

Form: 5.2.1D Page: Page 3 of 6 Date: 07 June 2018

Rev No. 1.2 Appr: BMM



MOB marker line attached to lifebuoy not of correct length



Lifeboat secured with turn buckle preventing its operational readiness at sea



Boat lashing plate frozen



Cradle swivel not freely turning



Expired HRU



Incorrectly mounted HRU



Bridge wing lifebuoys not weighing at least 4.0 KG to operate the quick release arrangement



Number of devices not indicated near LSA



Forward liferaft portable emergency light not operational

