



SAFETY, HEALTH, ENVIRONMENT AND QUALITY MANAGEMENT SYSTEM

PORT OF CALL HISTORY
REPORTING FORMS MANUALForm : 1.3.1B
Date : 02/June/2017
Rev : 1.0
App By : BMM**Port Feedback**

Ship Name	IVS MERLION
Port	MACKAY, AUSTRALIA
Terminal & Berth No.	BERTH no. 05

Port Details	
Anchorage approach	As per harbour master instruction
Min. depth at anchorage/Channel	Depth at anchorage 29m / Platypus Channel - 11.6 M
Pilot performance/Tugs condition	Vessel should request pilot 24h in advance / 2 tugs fwd & aft - heaving line required to retrieve tugs messenger, place eye of tugs line on 2nd bit away from fairlead
Other information	Pilot boards as follows: (a) Boarding Ground A: 21°07.03S 149°17'14E 3Miles ESE of the southern breakwater

Berth Details	
Berth Type	Dry cargo berth
Minimum depth at Berth/approach/UKC concern	Depth at Berth = 9.59 m / approach = 10.39 m / UKC concern = 0.43 m
Mooring arrangement	4 X 2 Fwd and Aft.
Berth Restrictions	Depth at Berth = 9.59 m / approach = 10.39 m / UKC concern = 0.43 m
Berth condition/fendering etc	Concrete berth with rubber fenders
Other information (fendering etc)	

Cargo Operation	
Manifold connections	N/A
Terminal courtesy/co-operation	VHF Ch 16; 12
Safety standard	Complete PPE required at berth.
Other information (booster pumps etc)	

Additional information	
Authorities(Custom/immig./health)	YES
Security (Stowaways/theft threats)	NIL
Spares/Stores/FW supply	NIL
Crew change/Shore leave	YES
General comments	
Recommendations	

Master's Name / Date	CAPT. CHARLIE TABUGO / 14 MACKAY 2019
----------------------	---------------------------------------