



SAFETY, HEALTH, ENVIRONMENT AND QUALITY MANAGEMENT SYSTEM

PORT OF CALL HISTORY

REPORTING FORMS MANUAL

Form : 1.3.1B
Date : 02/June/2017
Rev : 1.0
App By : BMM**Port Feedback**

Ship Name	IVS PHINDA
Port	LANSHAN, CHINA
Terminal & Berth No.	SOUTHERN BASIN, BERTH NO. 1

Port Details

Anchorage approach	Outer Anchorage No. 1, 2, 3, 4 along fairway channels. (Mud, sand, shells)
Min. depth at anchorage/Channel	MIN. DEPTH ANCHORAGE: 13.0m / CHANNEL: 13.0m
Pilot performance/Tugs condition	Good performance / tugs in good condition
Other information	Current: Others: Large no. of marine farms and fish traps within Lanshan port limits. Keep clear and avoid entry.

Berth Details

Berth Type	Concrete Construction Wharves
Minimum depth at Berth/approach/UKC concern	MIN. DEPTH AT BERTH: 14.1m, Starboard side alongside, MIN. UKC: 1.5m
Mooring arrangement	4 Head lines & Stern Lines with 2 Fwd & Back Spring Lines.
Berth Restrictions	No crew allowed while under cargo operation, Complete PPE required while at berth with visible vest.
Berth condition/fendering etc	Fully concrete berth with rubber fendering attached on side.
Other information (fendering etc)	BERTH Density 1.019 - 1.027 g/cm ³

Cargo Operation

Manifold connections	Ships Crane with 3 gangs, slings and log picker for loading.
Terminal courtesy/co-operation	Authorities and terminal personnel are cooperated.
Safety standard	Strict implementation of ISPS & PPE requirements.
Other information (booster pumps etc)	No walking is permitted whilst in port.

Additional information

Authorities(Custom/immig./health)	AGENT/ CUSTOMS/ IMMIG./ QUARANTINE ONBOARD
Security (Stowaways/theft threats)	SECURITY LEVEL 1
Spares/Stores/FW supply	Spares, Stores, FW Supply available to be arrange thru agent.
Crew change/Shore leave	Crew Change: YES, Shore leave: YES with shuttle van service to main gate.
General comments	Gangway & Mooring lines should be tended regularly. Adjusted & tight due to tides and large container vessels passing.
Recommendations	Observe safe working practices whilst handling mooring ropes.

Master's Name / Date	CAPT. RAYMOND M. SUMBANG / 20 NOV. 2019
----------------------	---