

SAFETY, HEALTH, ENVIRONMENT AND QUALITY MANAGEMENT SYSTEM

PORT OF CALL HISTORY

REPORTING FORMS MANUAL

Form: 1.3.1B Date: 02/June/2017 Rev: 1.0 App By: BMM

_	_		_
Por	+ 60	adh	ack

Ship Name	IVS PHINDA
Port	BATAM, INDONESIA
Terminal & Berth No.	Private Terminal

Port Details	
Anchorage approach	15.90 m
Min. depth at anchorage/Channel	12.90 m
Pilot performance/Tugs condition	Fair / Fair
Other information	Pilotage less than a Hour

Berth Details		
Berth Type	Dolphin / Starboard Side Alongside	
Minimum depth at Berth/approach/UKC concern	7.90m / 12.90m	
Mooring arrangement	FWD (4 Head Lines / / 2 Spring Line) / (2 Stern Lines / 2 Spring Lines / 1 Breast Line)	AFT
Berth Restrictions	YES	
Berth condition/fendering etc	Not good	
Other information (fendering etc)	Not good	

Cargo Operation	
Manifold connections	N/A
Terminal courtsey/co-operation	Fair
Safety standard	Fair - Poor
Other information (booster pumps etc)	Loading via Ships Crane

Additional information	
Authorities(Custom/immig./health)	Yes
Security (Stowaways/theft threats)	Security Level 1. Yes
Spares/Stores/FW supply	Yes
Crew change/Shore leave	No
General comments	Vessel was starboard side alongside to a barge which is moored
	to the dolphin. Vsls Fwd and Astern parts was exceeding the Barge. Also, Accessing the ship from shore side takes a lot of effort and jeopardizes safety due to that access is via Pilot Ladder which is height to climb is about 7-8 mtrs.
Recommendations	

Master's Name / Date	Capt. George S. Sarmiento