



SAFETY, HEALTH, ENVIRONMENT AND QUALITY MANAGEMENT SYSTEM

PORT OF CALL HISTORY

REPORTING FORMS MANUAL

Form : 1.3.1B
Date : 02/June/2017
Rev : 1.0
App By : BMM**Port Feedback**

Ship Name	IVS THANDA
Port	San Lorenzo
Terminal & Berth No.	ADM Transito Berth

Port Details

Anchorage approach	Drop Anchor on arrival at Reacalada anchorage as per instruction
Min. depth at anchorage/Channel	12.0 / 15.0
Pilot performance/Tugs condition	Only 1 tug fwd during departure / Pilot in good performance
Other information	Dropped Anchor during transit at Parana river and Zona common

Berth Details

Berth Type	Private terminal
Minimum depth at Berth/approach/UKC concern	13.5
Mooring arrangement	4 + 2 arrangement fwd & aft
Berth Restrictions	draft restriction 10.36m
Berth condition/fendering etc	Good
Other information (fendering etc)	Dropped stbd Anchor during berthing

Cargo Operation

Manifold connections	N/A
Terminal courtesy/co-operation	Good
Safety standard	Good
Other information (booster pumps etc)	Maize , SBM, Soya Hull Husk

Additional information

Authorities(Custom/immig./health)	Authorities onboard after ships alongside
Security (Stowaways/theft threats)	No stowaway threats in this port
Spares/Stores/FW supply	no supply in this port
Crew change/Shore leave	no crew change
General comments	
Recommendations	

Master's Name / Date

Capt Richard P. Gedalanga