

SAFETY, HEALTH, ENVIRONMENT AND QUALITY MANAGEMENT SYSTEM

PORT OF CALL HISTORY

REPORTING FORMS MANUAL

Form: 1.3.1B Date: 02/June/2017 Rev: 1.0 App By: BMM

Port Feedback

Ship Name	MV IVS NORTH BERWICK
Port	PORT REUNION, REUNION
Terminal & Berth No.	Berth No. 21

Port Details	
Anchorage approach	YES
Min. depth at anchorage/Channel	Anchorage - 28.0 mtrs / Berth - 16.0 mtrs
Pilot performance/Tugs condition	Satisfactory / 2 tugs, good condition
Other information	NIL

Berth Details	
Berth Type	Coal Terminal
Minimum depth at Berth/approach/UKC concern	12.7 mtrs / 16.0 mtrs / 2 mtrs UKC approach to berth
Mooring arrangement	Port side along side 4 + 2 fwd and aft.
Berth Restrictions	12.7 mtrs depth
Berth condition/fendering etc	Good
Other information (fendering etc)	NIL

Cargo Operation	
Manifold connections	N/A
Terminal courtsey/co-operation	Good
Safety standard	Good
Other information (booster pumps etc)	N/A

Additional information	
Authorities(Custom/immig./health)	Good
Security (Stowaways/theft threats)	Good (No stowaway & theft threat)
Spares/Stores/FW supply	Available
Crew change/Shore leave	Possible Crew change & shore leave
General comments	Cargo operation was smooth due to cooperative foremen
	and stevedores.
Recommendations	NIL
Master's Name / Date	Capt. Villorente / 19-Aug-2019