

SAFETY, HEALTH, ENVIRONMENT AND QUALITY MANAGEMENT SYSTEM

PORT OF CALL HISTORY

REPORTING FORMS MANUAL

Form: 1.3.1B Date: 02/June/2017 Rev: 1.0 App By: BMM

Port Feedback

Ship Name	IVS GLENEAGLES
Port	CAPE TOWN, SOUTH AFRICA
Terminal & Berth No.	BERTH "H" & "B"

Port Details	
Anchorage approach	Vessels may enter anywhere within the port limits, except for prohibited areas. Anchorage is prohibited in the dredged channel and approaches up to 2nm NNW of the breakwater light. Its SE corner is marked by a lightbuoy. The holding ground is not good in strong winds
Min. depth at anchorage/Channel	13.9m minimum charted depth at anchorage / sufficient for 12.3m draught for channeling
Pilot performance/Tugs condition	Satisfactory / 2 good Tugs used
Other information	ZACPT / Ø 33-54S λ 018-26E

Berth Details	
Berth Type	Wharf
Minimum depth at Berth/approach/UKC concern	Berth Depth 11.90m / Inner Breakwater depth 12.90m / sufficient UKC as per company policy
Mooring arrangement	F & A = 4+2
Berth Restrictions	Vessels carrying hazardous cargo or explosives are sometimes prohibited from berthing at night. Hazardous tankers are berthed during daylight only.
Berth condition/fendering etc	Good / Satisfactory
Other information (fendering etc)	Nil

Cargo Operation	
Manifold connections	N/A
Terminal courtsey/co-operation	Good
Safety standard	Good
Other information (booster pumps etc)	Nil

Additional information	
Authorities(Custom/immig./health)	Authorities came on board but only in the Gangway due to COVID-19 (AGENT/CUSTOM/IMMIG/HEALTH)
Security (Stowaways/theft threats)	ISPS compliant / MARSEC Level 2
Spares/Stores/FW supply	Available via Agent & Ship's Chandler. Received Food Provision Store
Crew change/Shore leave	Yes but temporarily banned due to COVID-19
General comments	1st Disport of Wheat / shifting operation carried-out
	Movements of shore & ship staffs during cargo operations was very limited due to COVID-19
	No Stowaway or security issues during the port stay
Recommendations	Maintain safety & security watch at all times. Ensure COVID-19 on board preventive measures are strictly implemented

Master's Name / Date	CAPT. GEORGE SARMIENTO / 30 APR 2020