

**PORT OF CALL HISTORY**
REPORTING FORMS MANUAL**Port Feedback**

Ship Name	IVS HIRONO
Port	DURBAN, S.A
Terminal & Berth No.	MAYDON WHARF, BERTH NR. 11

Port Details	
Anchorage approach	4 NM OUTSIDE B'WATER
Min. depth at anchorage/Channel	32
Pilot performance/Tugs condition	GOOD / GOOD
Other information	

Berth Details	
Berth Type	CONCRETE
Minimum depth at Berth/approach/UKC concern	10.2
Mooring arrangement	4X2 (4 - HEAD LINES / 2 - SPRING LINES)
Berth Restrictions	DRAFT 10.20m
Berth condition/fendering etc	GOOD
Other information (fendering etc)	PORT SIDE ALONGSIDE

Cargo Operation	
Manifold connections	N/A
Terminal courtesy/co-operation	GOOD
Safety standard	FAIR
Other information (booster pumps etc)	SHIPS CRANE AND GRAB WAS USED

Additional information	
Authorities(Custom/immig./health)	CUSTOMS ARE CONDUCTING CABIN SEARCHES
Security (Stowaways/theft threats)	YES. PORT SECURITY IS HIRED. DOG SEARCH ON DEPARTURE
Spares/Stores/FW supply	AVAILABLE
Crew change/Shore leave	AVAILABLE
General comments	STOWAWAY IS ENDEMIC. VIGILAN PORT AND GANG WAY WATHCES TO BE OBSVD.
Recommendations	

Master's Name / Date	CAPT. DARIUSZ J. SADLO / 22 MAY 2019
----------------------	--------------------------------------