

**PORT OF CALL HISTORY**
REPORTING FORMS MANUAL**Port Feedback**

Ship Name	IVS HIRONO
Port	RICHARDS BAY, Z.A.
Terminal & Berth No.	RBCT Berth 303

Port Details	
Anchorage approach	4 mile SE of South breakwater light
Min. depth at anchorage/Channel	18.6m
Pilot performance/Tugs condition	Pilot is very professional / Tugs good contion
Other information	

Berth Details	
Berth Type	CONCRETE
Minimum depth at Berth/approach/UKC concern	18.9m / adequate UKC
Mooring arrangement	FWD 4 headlines & 2 spring lines AFT 4 sternlines & 2 spring lines
Berth Restrictions	Nil
Berth condition/fendering etc	well maintained berth / good fender
Other information (fendering etc)	Turtle fender

Cargo Operation	
Manifold connections	N/A
Terminal courtesy/co-operation	Good cooperation
Safety standard	Normal
Other information (booster pumps etc)	

Additional information	
Authorities(Custom/immig./health)	Normal port formalities
Security (Stowaways/theft threats)	Shore watchman/stowaway prone area
Spares/Stores/FW supply	Available
Crew change/Shore leave	Possible
General comments	Vessel berthed portside alongside
Recommendations	

Master's Name / Date	Denis Diego / 21 Sept 2018
----------------------	----------------------------