

## SAFETY, HEALTH, ENVIRONMENT AND QUALITY MANAGEMENT SYSTEM

## PORT OF CALL HISTORY

## REPORTING FORMS MANUAL

Form: 1.3.1B Date: 02/June/2017 Rev: 1.0 App By: BMM

D4	$rac{1}{2}$	hack
POIT	reen	nack

1 Of 1 Coupack	
Ship Name	IVS Wentworth
Port	Bilbao, Spain
Terminal & Berth No.	Dry Bulk Terminal / Princesa Pier
Port Details	
i on botano	5 Designated Anchorage Areas at P/Stn vicinity, Port Control

Port Details	
	5 Designated Anchorage Areas at P/Stn vicinity, Port Control instructs vessels to anchor or drift awaiting berthing prospect.
Min. depth at anchorage/Channel	Depth at Anchor 18m
Pilot performance/Tugs condition	Good / Satisfactory
Other information	-

Berth Details	
Berth Type	Sheltered
Minimum depth at Berth/approach/UKC concern	Depth at Berth13.0m
Mooring arrangement	4+2 (F&A)
Berth Restrictions	Nil
Berth condition/fendering etc	Fairly clean condition with +- 20m bollard distance.
Other information (fendering etc)	Pontoon Type fendering used.

Cargo Operation	
Manifold connections	-
Terminal courtsey/co-operation	Satisfactory
Safety standard	High Safety Standard
Other information (booster pumps etc)	-

Additional information	
Authorities(Custom/immig./health)	Due to Covid-19 Pandemic, Agent handled all documentation.
Security (Stowaways/theft threats)	ISPS Port Compliant, Port is access controlled.
Spares/Stores/FW supply	Allowed, but not supply requested.
Crew change/Shore leave	Crew Change successfully carried out 2 Off 1 On / Shore Leave granted but Master denied shore leave due to COVID-19 Pandemic.
General comments	-
Recommendations	-

Master's Name / Date	Capt. Kenneth A. Brown / 31 Aug 2020