SOUTH AFRICA: URGENT STOWAWAY ADVICE

Published 02 November 2016

Member Advisory

Despite our previous loss prevention advice, stowaways continue to board vessels in South African ports far too frequently.

These attacks have increased significantly over the last two months. The South African authorities have made it abundantly clear they will not change their attitude and therefore the ship must combat unlawful individuals boarding the ship.

The current ruling in South Africa is as follows:

Should any unlawful person gain access onto a ship in a South African port, the person will automatically be deemed to be a stowaway unless the vessel can provide photographic, video or third party evidence (terminal security) that the stowaway attempted to board the vessel in Durban.

The ship owner will be liable for the full costs of repatriating the stowaway. It is essential therefore that the stowaway does not gain access onto the ship in any way.

We are now approaching Christmas and we believe that the rise in stowaway cases will increase as individuals look for free passage home.

We understand that ship owners are battling in the current economic conditions and do not wish to use private security and rely on the crew to police the ship.

Stowaway attacks occur as follows:

- · Late at night or early hours of the morning
- · Clothing easily blends-in with stevedore gangs wearing stevedore clothing hardhats and reflective jackets
- · Colours not easily seen at night
- Generally climb up berthing ropes, gangways and hide in empty containers and log-ships
- · Many personnel working on vessel enables stowaway to blend in
- They bribe terminal security to enable them to get aboard vessel
- · Carry provisions for part of the journey



Crew took pictures of the stowaway attempting to board the ship up the mooring lines

We recommend the following measures:

- The owner should try and employ private security to patrol the quayside. One security guard should be positioned on the forward mooring lines and one on the stern lines. Security on board is ineffective as the guards tend to fall asleep on board.
- Ideally a crew member must stand at the bottom of the gangway and check that every person boarding the vessel is in possession of a TNPA port permit.
- They must not allow anyone on board the ship who does not have a port permit.
- Every visitor should have ISPS clearance.
- All visitors should surrender their port permit to security and they should collect the same when they leave the ship.
- If anyone does not have a port permit, they must call the terminal/berth security in order to identify the individual and ascer who is the individual and why does the individual not have a TNPA port permit. The visitor should be in possession of photographic identification.
- They must not allow any individuals to push past them on the gangway. We have had repeated cases where individuals ha run past security at the top of the gangway. This is too late and the local authorities will deem the individual as being a stowaway.
- Where possible raise the gangway and only lower it and allow the visitor on board after a crew member has got to the bottom the gangway and verified who the visitor is as outlined above.

Should you have any queries please contact our office for advice and assistance.

P&I Associates (PTY) Ltd - Durban South Africa

Neil Chetty in Cape Town +27 83 250 3381
Roy Carby Thompson in Richards Bay +27 83 448 7787
Garth Hansen in Saldanha Bay +27 83 283 3493
David Macdonald in Durban +27 83 253 0170
Vishal Pragraj in Durban +27 83 441 5685
P&I Associates 24 hour duty number +27 83 250 3398

Michael Heads
Managing Director
P&I Associates (Pty) Ltd
Durban
South Africa
Tel: +27 31 301 1102

Fax: +27 31 301 1290 Mobile: +27 83 4534899 E-Mail: <u>headsm@pandi.co.za</u>

Disclaimer

The above article has been produced by or in co-operation with correspondents or other external sources and is reproduced here with their kind permission for general information purposes only. Reference is made to the <u>Legal disclaimer</u> governing use of this website.