

PSC deficiency at Kobe, Japan on 27 Aug 2025

No./Code	Description
1/07123	Crew in charge was not familiar with CO2 fire extinguishing system in Galley. Comments: - Please assess the knowledge of the crew members on the operation of fixed CO2 fire extinguishing system in Galley (where fitted). If required, conduct the familiarization training of the crew members on the operation of fixed CO2 fire extinguishing system. - Ensure clear operation instructions are posted near the CO₂ fire extinguishing system. - Crew should be familiar with the operation of all fire extinguishing systems fitted on board the vessel. - During monthly training as required by company Form 3.2.1, please ensure the training session is kept interactive with the crew members and assess their knowledge with the operation of fixed firefighting system. Refer fixed CO2 fire extinguishing system fitted in Galley on inspected vessel with operation instructions.  

Above has been read and understood.

C/O

2/O

3/O

D/C

2/E

3/E

4/E

ETO

E/C

Verified by: Master/CE

Please file signed copy in the shared drive 3.2.3 Training folder