

Fleet Advisory 2026-02

PSC deficiency at San Antonio, Chile on 05 Jan 2026

.No./ Code	Description
1/ 03102	Freeboard Marks/At Starboard side. Plimsoll mark and middle draft mark are not fully paint. <u>Comments:</u> - Inspect the load line and draft marks at each opportunity when vessel is alongside or at anchorage as marks get faded due to rubbing at berth fenders. - As and when required, please paint the marks after obtaining permission from Port Authority through agent for painting in port. Load Lines Regulation 8 - Details of marking == The ring, lines and letters shall be painted in white or yellow on a dark ground or in black on a light ground. They shall also be permanently marked on the sides of the ships to the satisfaction of the Administration. The marks shall be plainly visible and, if necessary, special arrangements shall be made for this purpose. == - The ring, lines and letters shall be painted in white (contrast colour for our fleet vessels)

Above has been read and understood.

C/O

2/O

3/O

D/C

Verified by: Master

Please file signed copy in the shared drive 3.2.3 Training folder