

OPPH HES

94

OPPH HZS

HEALTH, SAFETY, ENVIRONMENT AND QUALITY MANAGEMENT SYSTEM


51.0 GAS METER OPERATION, CALIBRATION AND BUMP TEST

ON THE JOB TRAINING

OJT: 051 Page 1 of 4 07-Nov-25 Date : 10.1 Rev: Appr: DPA

VESSEL:	DATE:

Details of Training: Gas Meter Operation, Calibration and Bump Test





HEALTH, SAFETY, ENVIRONMENT AND QUALITY MANAGEMENT SYSTEM

51.0 GAS METER OPERATION, CALIBRATION AND BUMP TEST


ON THE JOB TRAINING


OJT: 051 Page 2 of 4 Date: 07-Nov-25 Rev: 10.1


Rev: 10.1 Appr: DPA















HEALTH, SAFETY, ENVIRONMENT AND QUALITY MANAGEMENT SYSTEM

51.0 GAS METER OPERATION, CALIBRATION AND BUMP TEST

ON THE JOB TRAINING

OJT: 051 Page 3 of 4 07-Nov-25 Date : Rev: 10.1

DPA

Appr:



Auto Bump & Calibration












7

Insert





After the step 7, please follow the steps below to print the certificate -

- 1. Insert the USB stick into the calibration station, wait for 10 seconds till only 1 green LED light is shown
- 2. Take out the USB from the station and put it into the PC
- 3. Open the file in the USB stick and click on "PS200 Settings"
- 4. Click "View Test / Calibration Certificate"

- 4. Citck View lest / Calibration Certificate
 5. For "Customer Name" Put in vessel name
 6. For "Customer Detail 1" Put in company name
 7. For "Calibrated By"- Put in the name of the person who does the calibration
 8. You can leave all other fields blank
- 9. Click "Create Certificate"
- 10. Choose the relevant Test Result file and click Open
- 11. The calibration certificate is now generated. Print out the certificate and sign



HEALTH, SAFETY, ENVIRONMENT AND QUALITY MANAGEMENT SYSTEM

51.0 GAS METER OPERATION, CALIBRATION AND BUMP TEST

ON THE JOB TRAINING

OJT: 051
Page 4 of 4
Date: 07-Nov-25
Rev: 10.1
Appr: DPA

Calibration test:

- Put the USB stick into the PC
- Open the file in the USB stick and click on "PS200 Settings"
- Select "Calibration" instead of "Bump test". These settings are at the top of the box
- Click on generate test settings file and click "OK" when the next screen pop up
- Insert USB stick back into the USB station, and wait 30 seconds until the lights finish their cycle.
- When you see only one LED light, please remove the USB stick from the station
- Follow the steps in the attached pictorial guide step 1 to step 8

Reference: Maker manual

The above has been read and understood:

CO:		
20:		
30:		
JNO		
CEO		
2EO		
3EO		
4EO		
Verified by: Master		

Feedback: