
YANMAR SERVICE NEWS No.: 12-2-G-03-011-O Protection Ring Size Change Subject March 2013 Use Marine Aux. Engine 6EY18(A) L(W) Model Engine Nos.

The outer diameter size of the protection ring was changed, and the part code was changed accordingly as described below.

In the present change, the outer diameter of protection ring was made larger than that of the conventional protection ring in an aim to control carbon deposit. We have verified that there was no problem with the use of the changed protection ring in place of the conventional protection ring. This specification will be our standard specification hereafter.

Upon the engine servicing opportunities, check the protection ring according to the maintenance instructions given in the operation manual. If the ring has been worn exceeding the limit, replace the ring.

	Old	New
Part Code	146623-01120	146623-01121



YANMAR CO..LTD.

LARGE POWER PRODUCTS OPERATIONS DIV. QUALITY ASSURANCE DEPT.

FAX. No.: +81-6-6488-4009

Approved	Checked	Prepared
Modswage	4. Ta.	A. Yoshida