

SAFETY, HEALTH, ENVIRONMENT AND QUALITY MANAGEMENT SYSTEM

PORT OF CALL HISTORY

REPORTING FORMS MANUAL

Form: 1.3.1B Date: 02/June/2017 Rev: 1.0 App By: BMM

Port Feedback

Ship Name	MV IVS NORTH BERWICK
Port	ABBOT POINT, AUSTRALIA
Terminal & Berth No.	BERTH NO. 1

Port Details	
Anchorage approach	YES
Min. depth at anchorage/Channel	13m
Pilot performance/Tugs condition	GOOD
Other information	NIL

Berth Details	
Berth Type	GRAIN TERMINAL
Minimum depth at Berth/approach/UKC concern	19m/33m/6.28m
Mooring arrangement	4 head / stern line & 2 spring line fwd & aft
Berth Restrictions	19m
Berth condition/fendering etc	GOOD
Other information (fendering etc)	NIL

Cargo Operation	
Manifold connections	N/A
Terminal courtsey/co-operation	GOOD
Safety standard	GOOD
Other information (booster pumps etc)	NIL

Additional information	
Authorities(Custom/immig./health)	Good
Security (Stowaways/theft threats)	Good (No stowaway & theft threat)
Spares/Stores/FW supply	Available
Crew change/Shore leave	NIL Due to COVID-19 Pandemic
General comments	Cargo operation was smooth due to cooperative foremen
	and stevedores.
Recommendations	NIL

Master's Name / Date	Capt. Gimotea / 21-Mar-2020