



SAFETY, HEALTH, ENVIRONMENT AND QUALITY MANAGEMENT SYSTEM

**PORT OF CALL HISTORY**

REPORTING FORMS MANUAL

Form : 1.3.1B  
Date : 02/June/2017  
Rev : 1.0  
App By : BMM**Port Feedback**

Ship Name	IVS MERLION
Port	ALBANY, AUSTRALIA
Terminal & Berth No.	ALBANY GRAIN JETTY - BERTH NO.3

**Port Details**

Anchorage approach	As per harbour master instruction
Min. depth at anchorage/Channel	14 mtrs
Pilot performance/Tugs condition	Pilotage is compulsory for all vessels over 150 gt.
Other information	Pilot boards in position 35°04'·00S 118°00'·00E

**Berth Details**

Berth Type	Dry cargo berth
Minimum depth at Berth/approach/UKC concern	12,2 M
Mooring arrangement	3x1x2 Fwd and Aft.
Berth Restrictions	BEAM - 32.3M / LOA - 225M
Berth condition/fendering etc	Concrete berth with rubber fenders
Other information (fendering etc)	

**Cargo Operation**

Manifold connections	N/A
Terminal courtesy/co-operation	VHF CH. 12 / +61(0)4 88929095
Safety standard	Complete PPE required at berth.
Other information (booster pumps etc)	

**Additional information**

Authorities(Custom/immig./health)	YES
Security (Stowaways/theft threats)	NIL
Spares/Stores/FW supply	YES
Crew change/Shore leave	YES
General comments	
Recommendations	

Master's Name / Date

CAPT. RICHARD P. GEDALANGA / 29 MAY 2019