



SAFETY, HEALTH, ENVIRONMENT AND QUALITY MANAGEMENT SYSTEM

PORT OF CALL HISTORY

REPORTING FORMS MANUAL

Form : 1.3.1B
Date : 02/June/2017
Rev : 1.0
App By : BMM**Port Feedback**

Ship Name	IVS MERLION
Port	DEVONPORT, AUSTRALIA
Terminal & Berth No.	WEST WHARF BERTH NO. 4

Port Details

Anchorage approach	No specified anchorage area / anchorage at the port outside limit
Min. depth at anchorage/Channel	8.5 mtrs
Pilot performance/Tugs condition	Pilot are compulsory with 2 tugs / Good
Other information	Pilot VHF Ch. 12, 16

Berth Details

Berth Type	WHARF
Minimum depth at Berth/approach/UKC concern	7.7m
Mooring arrangement	4 X 2 Fwd and Aft lines.
Berth Restrictions	Max LOA 230mtrs, draught 10,8mtrs
Berth condition/fendering etc	Concrete type with rubber fender.
Other information (fendering etc)	

Cargo Operation

Manifold connections	Hopper with grab / ship's crane
Terminal courtesy/co-operation	Port Personnel cooperate well
Safety standard	Complete PPE require at port area.
Other information (booster pumps etc)	Working hours 24 /7

Additional information

Authorities(Custom/immig./health)	YES
Security (Stowaways/theft threats)	NO
Spares/Stores/FW supply	YES
Crew change/Shore leave	YES
General comments	
Recommendations	

Master's Name / Date

CAPT. CHARLIE T. TABUGO / 03 NOV 2019