

## SAFETY, HEALTH, ENVIRONMENT AND QUALITY MANAGEMENT SYSTEM

## PORT OF CALL HISTORY

## REPORTING FORMS MANUAL

Form: 1.3.1B Date: 02/June/2017 Rev: 1.0 App By: BMM

## Port Feedback

Ship Name	IVS THANDA
Port	HOBART, AUSTRALIA
Terminal & Berth No.	MACQUARIE WHARF NO. 4

Port Details	
Anchorage approach	N/A
Min. depth at anchorage/Channel	20m / 16.3m
Pilot performance/Tugs condition	SATISFACTORY / GOOD CONDITION
Other information	

Berth Details	
Berth Type	CONCRETE / FENDERED
Minimum depth at Berth/approach/UKC concern	12.6m / 21.3m / NIL
Mooring arrangement	4 + 2 FWD & AFT
Berth Restrictions	COVID-19 PRECAUTIONS
Berth condition/fendering etc	GOOD / SATISFACTORY
Other information (fendering etc)	

Cargo Operation	
Manifold connections	N/A
Terminal courtsey/co-operation	GOOD / SATISFACTORY
Safety standard	SATISFACTORY
Other information (booster pumps etc)	N/A

Additional information	
Authorities(Custom/immig./health)	AUTHORITIES CLEARED AT BERTH
Security (Stowaways/theft threats)	MARSEC LEVEL 1
Spares/Stores/FW supply	NIL
Crew change/Shore leave	NIL / NIL DUE TO COVID-19 PRECAUTIONS
General comments	VESSEL WILL LOAD LOGS - 23,315 MT / ESTIMATED OPERATION TIME WILL BE 3 DAYS
Recommendations	

Master's Name / Date	ADAM BORNA / 02-08-2020
----------------------	-------------------------