



SAFETY, HEALTH, ENVIRONMENT AND QUALITY MANAGEMENT SYSTEM

**PORT OF CALL HISTORY**

REPORTING FORMS MANUAL

Form : 1.3.1B  
Date : 02/June/2017  
Rev : 1.0  
App By : BMM**Port Feedback**

Ship Name	IVS SPARROWHAWK
Port	Karumba Australia
Terminal & Berth No.	Roadstead anchorage

**Port Details**

Anchorage approach	Roadstead anchorage area
Min. depth at anchorage/Channel	10.6m
Pilot performance/Tugs condition	No pilot or tugs
Other information	Only anchorage due to shallow water

**Berth Details**

Berth Type	NIL
Minimum depth at Berth/approach/UKC concern	4.3m
Mooring arrangement	NIL
Berth Restrictions	NIL
Berth condition/fendering etc	NIL
Other information (fendering etc)	-

**Cargo Operation**

Manifold connections	NIL
Terminal courtesy/co-operation	Good
Safety standard	Safety standards practice
Other information (booster pumps etc)	-

**Additional information**

Authorities(Custom/immig./health)	None
Security (Stowaways/theft threats)	None
Spares/Stores/FW supply	None
Crew change/Shore leave	None
General comments	Vessel on anchorage loading only
Recommendations	

Master's Name / Date

Capt. Lucian Filat / 12 Mar 2020