



SAFETY, HEALTH, ENVIRONMENT AND QUALITY MANAGEMENT SYSTEM

PORT OF CALL HISTORY

REPORTING FORMS MANUAL

Form : 1.3.1B
Date : 02/June/2017
Rev : 1.0
App By : BMM**Port Feedback**

Ship Name	IVS MERLION
Port	KWINANA, AUSTRALIA
Terminal & Berth No.	KWINANA BERTH NO. 3

Port Details

Anchorage approach	Gage roads anchorage as instructed by harbour master.
Min. depth at anchorage/Channel	9.0 mtrs
Pilot performance/Tugs condition	Pilot are compulsory with 2 tugs.
Other information	over 11mtrs draught - Outer PBG / less 11mtrs draught - Inner PBG.

Berth Details

Berth Type	Bulk Jetty
Minimum depth at Berth/approach/UKC concern	12.3M draught
Mooring arrangement	4 X 2 Fwd and Aft lines.
Berth Restrictions	LOA 244 mtrs and Depth 13.4mtrs
Berth condition/fendering etc	Concrete type with rubber fender.
Other information (fendering etc)	

Cargo Operation

Manifold connections	Self unloader cranes with grabs.
Terminal courtesy/co-operation	Port Personnel cooperate well
Safety standard	Complete PPE require at port area.
Other information (booster pumps etc)	Working hours 08-15 / 15-22 / 01-07

Additional information

Authorities(Custom/immig./health)	YES
Security (Stowaways/theft threats)	NO
Spares/Stores/FW supply	YES
Crew change/Shore leave	YES
General comments	
Recommendations	

Master's Name / Date	CAPT. RICHARD P. GEDALANGA / 01 Mar. 2019
----------------------	---