

## SAFETY, HEALTH, ENVIRONMENT AND QUALITY MANAGEMENT SYSTEM

## PORT OF CALL HISTORY

## REPORTING FORMS MANUAL

Form : 1.3.1B Date : 02/June/2017

Rev : 1.0 App By : BMM

## Port Feedback

Ship Name	IVS MERLION
Port	VANCOUVER WASHINGTON, USA
Terminal & Berth No.	BERTH No.7 KINDER MORGAN BULK TERMINAL

Port Details	
Anchorage approach	ANCHOR AT COLUMBIA RIVER, UPPER VANCOUVER ANCHORAGE
Min. depth at anchorage/Channel	18 MTR ANCHORAGE /12.0 MTR BERTH DEPTH
Pilot performance/Tugs condition	GOOD
Other information	NIL.

Berth Details	
Berth Type	BULK TERMINAL
Minimum depth at Berth/approach/UKC concern	14.0 MTR BERTH DEPTH
Mooring arrangement	PORT SIDE ALONGSIDE 4-2-2 (FORWARD & AFT)
Berth Restrictions	
Berth condition/fendering etc	GOOD
Other information (fendering etc)	NIL

Cargo Operation	
Manifold connections	N/A
Terminal courtsey/co-operation	GOOD
Safety standard	GOOD
Other information (booster pumps etc)	FIXED SHORE CARGO CONVEYOR

Additional information	
Authorities(Custom/immig./health)	YES
Security (Stowaways/theft threats)	YES / NO STOWAWAYS & NO THREATS
Spares/Stores/FW supply	YES
Crew change/Shore leave	YES
General comments	
Recommendations	

Master's Name / Date	DARIUSZ WIEWIORKOWSKI / 11 FEB. 2018
	A STATE OF THE PARTY OF THE PAR

