

SAFETY, HEALTH, ENVIRONMENT AND QUALITY MANAGEMENT SYSTEM

PORT OF CALL HISTORY

REPORTING FORMS MANUAL

Form : 1.3.1B Date : 02/June/2017 Rev : 1.0 App By : BMM

Port Feedback	
Ship Name	IVS THANDA
Port	Hong kong, China
Terminal & Berth No.	SW LAMMA, Anchorage
Port Details	
Anchorage approach	YES
Min. depth at anchorage/Channel	22m
Pilot performance/Tugs condition	NIL
Other information	
Berth Details	
Berth Type	N/A
Minimum depth at Berth/approach/UKC concern	N/A
Mooring arrangement	N/A
Berth Restrictions	N/A
Berth condition/fendering etc	Good
Other information (fendering etc)	
Cargo Operation	
Manifold connections	YES
Terminal courtsey/co-operation	Good
Safety standard	Good
Other information (booster pumps etc)	BALLAST
Additional information	
Authorities(Custom/immig./health)	NIL
Security (Stowaways/theft threats)	No stowaway threats in this port
Spares/Stores/FW supply	545.25MT (HSFO)
Crew change/Shore leave	nil
General comments	
Recommendations	
Masteria Nama / Data	Cont Dishard D. Codelange

Master's Name / Date

Capt Richard P. Gedalanga