

**PORT OF CALL HISTORY**  
REPORTING FORMS MANUAL**Port Feedback**

Ship Name	IVS HIRONO
Port	HRDD, SHANGHAI
Terminal & Berth No.	DOCK YARD

<b>Port Details</b>	
Anchorage approach	CHOMMING ANCHORAGE
Min. depth at anchorage/Channel	25
Pilot performance/Tugs condition	Pilot is Good / Fair Tug Boats
Other information	VARIOUS BERTH

<b>Berth Details</b>	
Berth Type	Concrete , Jetty and floating dock
Minimum depth at Berth/approach/UKC concern	15m
Mooring arrangement	FWD 4 headlines & 2 spring lines AFT 4 sternlines & 2 spring lines
Berth Restrictions	Nil
Berth condition/fendering etc	well maintained clean berth / good fender
Other information (fendering etc)	

<b>Cargo Operation</b>	
Manifold connections	N/A
Terminal courtesy/co-operation	Good cooperation
Safety standard	Normal
Other information (booster pumps etc)	

<b>Additional information</b>	
Authorities(Custom/immig./health)	Normal port formalities
Security (Stowaways/theft threats)	Security at main gate
Spares/Stores/FW supply	YES
Crew change/Shore leave	N/A Due to Pandemic warning
General comments	Dry Dock
Recommendations	

Master's Name / Date	CAPT. A. BATA/28 JUNE 2020
----------------------	----------------------------