



PORT OF CALL HISTORY

REPORTING FORMS MANUAL

Port Feedback

Ship Name	IVS BOSCH HOEK
Port	HRDD SHANGHAI
Terminal & Berth No.	BERTH NO.7

Port Details

Anchorage approach	CJK ANCHORAGE
Min. depth at anchorage/Channel	23m / 6.0m
Pilot performance/Tugs condition	SATISFACTORY
Other information	N/A

Berth Details

Berth Type	FLOATING DOCK
Minimum depth at Berth/approach/UKC concern	11.0m / 10.0m / 6.0m
Mooring arrangement	4 - 2 FWD & AFT
Berth Restrictions	NIL
Berth condition/fendering etc	SATISFACTORY
Other information (fendering etc)	SATISFACTORY

Cargo Operation

Manifold connections	N/A
Terminal courtesy/co-operation	SATISFACTORY
Safety standard	AS PER PORT ADVISED
Other information (booster pumps etc)	N/A

Additional information

Authorities(Custom/immig./health)	29 SEP. 2018
Security (Stowaways/theft threats)	NIL
Spares/Stores/FW supply	NIL
Crew change/Shore leave	YES
General comments	SAFELY BERTHED
Recommendations	

Master's Name / Date

CAPT. BRIAN COXON / 29 SEP. 2018