

Port Feedback Ship Name SAFETY, HEALTH, ENVIRONMENT AND QUALITY MANAGEMENT SYSTEM

PORT OF CALL HISTORY

REPORTING FORMS MANUAL

Form : 1.3.1B Date : 02/June/2017 Rev : 1.0 App By : BMM

DRTING FORMS MANUAL		
	IVS THANDA	
	PUTIAN, CHINA	

Port	PUTIAN, CHINA
Terminal & Berth No.	Potou Terminal
Port Details	
Anchorage approach	yes
Min. depth at anchorage/Channel	22m
Pilot performance/Tugs condition	2 tugs used / Pilot in good performance
Other information	
Berth Details	
Berth Type	Logs terminal
Minimum depth at Berth/approach/UKC concern	13.0M
Mooring arrangement	4 + 2 arrangement fwd & aft
Berth Restrictions	no restriction
Berth condition/fendering etc	Good
Other information (fendering etc)	
Cargo Operation	
Manifold connections	N/A
Terminal courtsey/co-operation	Good
Safety standard	Good
Other information (booster pumps etc)	Logs
Additional information	
Authorities(Custom/immig./health)	Authorities onboard after ships alongside
Security (Stowaways/theft threats)	No stowaway threats in this port
Spares/Stores/FW supply	deck, galley & engine received
Crew change/Shore leave	yes
General comments	
Recommendations	

Master's Name / Date

Capt KRZYSZTOF M. MUCZYNSKI