

SAFETY, HEALTH, ENVIRONMENT AND QUALITY MANAGEMENT SYSTEM

PORT OF CALL HISTORY

REPORTING FORMS MANUAL

Form: 1.3.1B Date: 02/June/2017 Rev: 1.0 App By: BMM

Port Feedback

Ship Name	IVS Swinley Forest
Port	Dunkirk, France
Terminal & Berth No.	East Terminal

Port Details	
Anchorage approach	Dunkirk Anchorage
Min. depth at anchorage/Channel	13m along the channel
Pilot performance/Tugs condition	Good / 2 tug used during unberthing
Other information	

Berth Details	
Berth Type	Quay
Minimum depth at Berth/approach/UKC concern	18m along berth & 13m along channel
Mooring arrangement	4 Headlines & 2 Fwd spring lines / 4 Astern Lines & 2 Aft spring Lines
Berth Restrictions	nil
Berth condition/fendering etc	Good condition
Other information (fendering etc)	nil

Cargo Operation	
Manifold connections	discharging manganese ore using shore facilities
Terminal courtsey/co-operation	Good
Safety standard	High
Other information (booster pumps etc)	

Additional information	
Authorities(Custom/immig./health)	Good
Security (Stowaways/theft threats)	no issue
Spares/Stores/FW supply	nil
Crew change/Shore leave	No/shore leave allowed
General comments	Very good, no problem acquired
Recommendations	

Master's Name / Date	Capt. James Vic Legason