



PORT OF CALL HISTORY

REPORTING FORMS MANUAL

Port Feedback

Ship Name	IVS BOSCH HOEK
Port	KANDLA
Terminal & Berth No.	BERTH NO.10

Port Details

Anchorage approach	KANDLA ANCHORAGE
Min. depth at anchorage/Channel	7.7m
Pilot performance/Tugs condition	SATISFACTORY
Other information	N/A

Berth Details

Berth Type	MULTIPURPOSE TERMINAL
Minimum depth at Berth/approach/UKC concern	13.5m / 7.7m / 1.3m
Mooring arrangement	3-2-2 FWD & AFT
Berth Restrictions	NIL
Berth condition/fendering etc	SATISFACTORY
Other information (fendering etc)	SATISFACTORY

Cargo Operation

Manifold connections	N/A
Terminal courtesy/co-operation	SATISFACTORY
Safety standard	AS PER PORT ADVISED
Other information (booster pumps etc)	N/A

Additional information

Authorities(Custom/immig./health)	09 NOV. 2018
Security (Stowaways/theft threats)	NIL
Spares/Stores/FW supply	NIL
Crew change/Shore leave	YES
General comments	SAFELY BERTHED
Recommendations	

Master's Name / Date

CAPT. PIOTR MACIEJ MONTWILL / 09 NOV. 2018