

Port Feedback

SAFETY, HEALTH, ENVIRONMENT AND QUALITY MANAGEMENT SYSTEM

PORT OF CALL HISTORY

REPORTING FORMS MANUAL

Form : 1.3.1B Date : 02/June/2017 Rev : 1.0 App By : BMM

Ship Name	IVS WENTWORTH
Port	MAGDALLA, INDIA
Terminal & Berth No.	MAGDALLA ANCHORAGE, INDIA
Port Details	
Anchorage approach	Available depth 25.0 m.
Min. depth at anchorage/Channel	24.06m
Pilot performance/Tugs condition	NIL
Other information	Magdalla Port Control VHF CH. 09/16/71
Berth Details	
Berth Type	Anchorage
Minimum depth at Berth/approach/UKC concern	24.06m
Mooring arrangement	NIL
Berth Restrictions	NIL
Berth condition/fendering etc	NIL
Other information (fendering etc)	NIL
Cargo Operation	
Manifold connections	NIL
Terminal courtsey/co-operation	NIL
Safety standard	NIL
Other information (booster pumps etc)	NIL
Additional information	
Authorities(Custom/immig./health)	Satisfactory
Security (Stowaways/theft threats)	Additional Security watch on deck/bridge watch
Spares/Stores/FW supply	Received FW
Crew change/Shore leave	NIL
General comments	
Recommendations	Fishing boats are dense and sometimes put fishing markers inside the TSS. Sharp look out must be maintained at all times.
Master's Name / Date	Capt. Krzysztof Z. Senczuk