



SAFETY, HEALTH, ENVIRONMENT AND QUALITY MANAGEMENT SYSTEM

PORT OF CALL HISTORY

REPORTING FORMS MANUAL

Form : 1.3.1B
Date : 02/June/2017
Rev : 1.0
App By : BMM**Port Feedback**

Ship Name	IVS OKUDOGO
Port	Mundra, India
Terminal & Berth No.	Terminal 3 Berth 10

Port Details

Anchorage approach	General Anchorage A South of PBGB
Min. depth at anchorage/Channel	18m
Pilot performance/Tugs condition	Satisfactory / Good
Other information	Speed of less than 3 kts at PSTN

Berth Details

Berth Type	Concreted quay
Minimum depth at Berth/approach/UKC concern	14.0m
Mooring arrangement	4 + 2 Fwd & Aft
Berth Restrictions	NIL
Berth condition/fendering etc	Satisfactory
Other information (fendering etc)	Satisfactory

Cargo Operation

Manifold connections	N/A
Terminal courtesy/co-operation	Satisfactory
Safety standard	Satisfactory / As per port advice
Other information (booster pumps etc)	3 shore crane available

Additional information

Authorities(Custom/immig./health)	18 November 2019 upon arrival.
Security (Stowaways/theft threats)	NIL
Spares/Stores/FW supply	NIL
Crew change/Shore leave	NIL / No shore pass issued - only allowed on duty free at port
General comments	Safely Berthed
Recommendations	

Master's Name / Date

Capt. Brian Coxon / 21 November 2019