

SAFETY, HEALTH, ENVIRONMENT AND QUALITY MANAGEMENT SYSTEM

PORT OF CALL HISTORY

REPORTING FORMS MANUAL

Form: 1.3.1B Date: 02/June/2017 Rev: 1.0 App By: BMM

P٥	-4	\mathbf{E}_{\sim}	 ha	~ -
-()		-	 107	IL:K

Recommendations

Port Feedback			
Ship Name	IVS NORTH BERWICK		
Port	PORBANDAR, INDIA		
Terminal & Berth No.			
Port Details			
Anchorage approach	1.29NM SW OF BREAKWATER		
Min. depth at anchorage/Channel	17m / 8m		
Pilot performance/Tugs condition	Good / Good (Ships Lines)		
Other information	LIGHTERING REQUIRED BEFORE BERTHING		
Berth Details			
Berth Type	Multi purpose concrete quay		
Minimum depth at Berth/approach/UKC concern	8m / 9m / nil after lightering at anchor		
Mooring arrangement	FWD 2+2+2 / AFT 4+2		
Berth Restrictions	Nil		
Berth condition/fendering etc	Filthy, in disrepair / Tires		
Other information (fendering etc)			
Cargo Operation			
Manifold connections	NA		
Terminal courtsey/co-operation	GOOD / GOOD		
Safety standard	POOR		
Other information (booster pumps etc)	NA		
Additional information			
Authorities(Custom/immig./health)	FAIR		
Security (Stowaways/theft threats)	Appears vulnerable but no issues experienced. Did not use guards.		
Spares/Stores/FW supply	NA / YES / YES		
Crew change/Shore leave	NA		
General comments			

Master's Name / Date	Capt. Mike Melly / 30 OCT 2020