

SAFETY, HEALTH, ENVIRONMENT AND QUALITY MANAGEMENT SYSTEM

PORT OF CALL HISTORY

REPORTING FORMS MANUAL REPORTING FORMS MANUAL

Form: 1.3.1B Date: 02/June/2017 Rev: 1.0 App By: BMM

Port Feedback

Ship Name	IVS Wentworth
Port	Tuticorin, India
Terminal & Berth No.	VOC Berth 6

Port Details	
Anchorage approach	4 Designated Anchorage Areas, Whereby 2 of which can be assigned for Bulk Carriers, Also have a designated lighterage Anchorage available further out to sea in deeper waters.
Min. depth at anchorage/Channel	Channel Dredged to 14.10m
Pilot performance/Tugs condition	Good / Satisfactory
Other information	-

Berth Details	
Berth Type	Sheltered
Minimum depth at Berth/approach/UKC concern	Min. UKC at Berth = 5.50m
Mooring arrangement	4+2 (F & A)
Berth Restrictions	Nil
Berth condition/fendering etc	Minimal Attention to Quay Maintenance / Fenders in good condition.
Other information (fendering etc)	Tyre-Type Fenders

Cargo Operation	
Manifold connections	-
Terminal courtsey/co-operation	Good
Safety standard	Minimum Safety Standard
Other information (booster pumps etc)	-

Additional information	
Authorities(Custom/immig./health)	Agent / Immigrating / Customs / Port Health
Security (Stowaways/theft threats)	ISPS Port Compliant, Port is access controlled.
Spares/Stores/FW supply	Allowed, but not supply requested.
Crew change/Shore leave	Crew Change not permitted / No Shore Leave granted due to COVID-19 Pandemic.
General comments	Port Documents to be up to date with proper information, to avoid penalties.
Recommendations	

Master's Name / Date	Capt. Kenneth A. Brown / 28 Oct 2020