



SAFETY, HEALTH, ENVIRONMENT AND QUALITY MANAGEMENT SYSTEM

PORT OF CALL HISTORY

REPORTING FORMS MANUAL

Form : 1.3.1B
Date : 02/June/2017
Rev : 1.0
App By : BMM**Port Feedback**

Ship Name	IVS OKUDOGO
Port	Bahodopi, Morowali, Indonesia
Terminal & Berth No.	Bintang Delapan Terminal / Jetty Berth No.1

Port Details

Anchorage approach	Bahodopi Anchorage
Min. depth at anchorage/Channel	36.0m
Pilot performance/Tugs condition	Satisfactory
Other information	N/A

Berth Details

Berth Type	Multipurpose Jetty Terminal / Concrete construction / Protected with moder rubber finders
Minimum depth at Berth/approach/UKC concern	16.8m / 37m / 6m
Mooring arrangement	4 - 2 Fwd & Aft
Berth Restrictions	No restriction / Terminal can handled more than 100grt vessels.
Berth condition/fendering etc	Satisfactory
Other information (fendering etc)	Satisfactory

Cargo Operation

Manifold connections	N/A
Terminal courtesy/co-operation	Good
Safety standard	As per port advised
Other information (booster pumps etc)	N/A

Additional information

Authorities(Custom/immig./health)	17 Nov 20
Security (Stowaways/theft threats)	NIL
Spares/Stores/FW supply	N/A
Crew change/Shore leave	Not allowed
General comments	Safely Berthed
Recommendations	ALWAYS SECURE RAT GUARDS AND SHOULD BE VIGILANT IN PORT WATCH.
Master's Name / Date	CAPT. GODFREY G. GIMOTEA / 19 Nov. 2020