



SAFETY, HEALTH, ENVIRONMENT AND QUALITY MANAGEMENT SYSTEM

**PORT OF CALL HISTORY**

REPORTING FORMS MANUAL

Form : 1.3.1B  
Date : 02/June/2017  
Rev : 1.0  
App By : BMM**Port Feedback**

Ship Name	IVS HIRONO
Port	BONTANG, INDONESIA
Terminal & Berth No.	BONTANG COAL TERMINAL

**Port Details**

Anchorage approach	BONTANG ANCHORAGE
Min. depth at anchorage/Channel	20 M
Pilot performance/Tugs condition	GOOD SHIP HANDLING
Other information	JETTY WITH LOADING CONVEYOR

**Berth Details**

Berth Type	JETTY, CONCRETE STRUCTURE
Minimum depth at Berth/approach/UKC concern	18 M / 3 M AT JETTY
Mooring arrangement	FWD 4 headlines & 2 spring lines AFT 4 sternlines & 2 spring lines
Berth Restrictions	COVID19 RESTRICTION, NO SHORE LEAVE
Berth condition/fendering etc	GOOD CONDITION
Other information (fendering etc)	HEAVY RUBBER FENDER

**Cargo Operation**

Manifold connections	N/A
Terminal courtesy/co-operation	Good cooperation
Safety standard	Normal
Other information (booster pumps etc)	

**Additional information**

Authorities(Custom/immig./health)	Normal port formalities
Security (Stowaways/theft threats)	COVID19 RESTRICTION
Spares/Stores/FW supply	NIL
Crew change/Shore leave	NO CREW CHANGE AND NO SHORE LEAVE
General comments	LIMITED PERSON ONBOARD
Recommendations	

Master's Name / Date      CAPT. A. BATA/29 JULY 2020