



SAFETY, HEALTH, ENVIRONMENT AND QUALITY MANAGEMENT SYSTEM

**PORT OF CALL HISTORY**

REPORTING FORMS MANUAL

Form : 1.3.1B  
Date : 02/June/2017  
Rev : 1.0  
App By : BMM**Port Feedback**

Ship Name	IVS SPARROWHAWK
Port	KENDAWANGAN, INDONESIA
Terminal & Berth No.	ANCHOR BERTH

**Port Details**

Anchorage approach	Vessel anchored on position given by Agent.
Min. depth at anchorage/Channel	Depth of Anchorage area abt 24.0m
Pilot performance/Tugs condition	N/A
Other information	Kendawangan Port has no berth for vessels only loading facilities for Alumina in the Anchorage area using barges.

**Berth Details**

Berth Type	N/A
Minimum depth at Berth/approach/UKC concern	N/A
Mooring arrangement	N/A
Berth Restrictions	N/A
Berth condition/fendering etc	N/A
Other information (fendering etc)	

**Cargo Operation**

Manifold connections	N/A
Terminal courtesy/co-operation	Good and approachable.
Safety standard	Safety standards are poor.
Other information (booster pumps etc)	N/A

**Additional information**

Authorities(Custom/immig./health)	Professional and courteous.
Security (Stowaways/theft threats)	ISPS compliant port.
Spares/Stores/FW supply	No Ship's store received/ FW received from brage's tugs
Crew change/Shore leave	No Crew change/ No shore leave for the crew
General comments	Good sheltered port.
Recommendations	

Master's Name / Date: 07 May 2019

Capt. Celso C. Torlao Jr