



SAFETY, HEALTH, ENVIRONMENT AND QUALITY MANAGEMENT SYSTEM

PORT OF CALL HISTORY

REPORTING FORMS MANUAL

Form : 1.3.1B
Date : 02/June/2017
Rev : 1.0
App By : BMM**Port Feedback**

Ship Name	IVS OKUDOGO
Port	Morosi, Kendari, Indonesia
Terminal & Berth No.	Morosi Anchorage

Port Details

Anchorage approach	Morosi East Sulawesi coast
Min. depth at anchorage/Channel	30.0m
Pilot performance/Tugs condition	Satisfactory
Other information	Anchorage area congested

Berth Details

Berth Type	Anchorage Area
Minimum depth at Berth/approach/UKC concern	N/A
Mooring arrangement	N/A
Berth Restrictions	N/A
Berth condition/fendering etc	N/A
Other information (fendering etc)	N/A

Cargo Operation

Manifold connections	N/A
Terminal courtesy/co-operation	Good
Safety standard	As per port advised
Other information (booster pumps etc)	N/A

Additional information

Authorities(Custom/immig./health)	10 Nov 20
Security (Stowaways/theft threats)	To be vigilant due to plenty fishing boat around the area.
Spares/Stores/FW supply	N/A
Crew change/Shore leave	Not allowed
General comments	Safely Anchored
Recommendations	

Master's Name / Date

CAPT. GODFREY G. GIMOTEA / 10 Nov. 2020