



SAFETY, HEALTH, ENVIRONMENT AND QUALITY MANAGEMENT SYSTEM

PORT OF CALL HISTORY

REPORTING FORMS MANUAL

Form : 1.3.1B
Date : 02/June/2017
Rev : 1.0
App By : BMM**Port Feedback**

Ship Name	IVS Swinley Forest
Port	Muara Berau
Terminal & Berth No.	Supramax Loading Area

Port Details

Anchorage approach	Supramax Loading Area
Min. depth at anchorage/Channel	20m
Pilot performance/Tugs condition	Satisfactory / Good
Other information	Swell greatly affects vessel movement at times

Berth Details

Berth Type	Anchorage
Minimum depth at Berth/approach/UKC concern	20m
Mooring arrangement	N/A
Berth Restrictions	N/A
Berth condition/fendering etc	N/A
Other information (fendering etc)	Good holding ground

Cargo Operation

Manifold connections	Loading via ship's crane and grab
Terminal courtesy/co-operation	Satisfactory
Safety standard	Satisfactory / As per port advice
Other information (booster pumps etc)	NIL

Additional information

Authorities(Custom/immig./health)	19 Oct. 2020
Security (Stowaways/theft threats)	NIL / hydrant caps and spanners secured
Spares/Stores/FW supply	NIL
Crew change/Shore leave	NIL
General comments	Anchored safely
Recommendations	

Master's Name / Date

Capt. Mirosław Bogusław Kaczmarczyk / 29 October 2020