

**PORT OF CALL HISTORY**
REPORTING FORMS MANUAL**Port Feedback**

| | |
|----------------------|-----------------------|
| Ship Name | IVS BOSCH HOEK |
| Port | SAMARINDA |
| Terminal & Berth No. | MUARA BERAU ANCHORAGE |

Port Details

| | |
|----------------------------------|-----------------------|
| Anchorage approach | MUARA BERAU ANCHORAGE |
| Min. depth at anchorage/Channel | 32m / 41m |
| Pilot performance/Tugs condition | SATISFACTORY |
| Other information | N/A |

Berth Details

| | |
|---|-----------------|
| Berth Type | ANCHORAGE |
| Minimum depth at Berth/approach/UKC concern | 36m / 36m / 29m |
| Mooring arrangement | N/A |
| Berth Restrictions | N/A |
| Berth condition/fendering etc | SATISFACTORY |
| Other information (fendering etc) | SATISFACTORY |

Cargo Operation

| | |
|---------------------------------------|---------------------|
| Manifold connections | N/A |
| Terminal courtesy/co-operation | SATISFACTORY |
| Safety standard | AS PER PORT ADVISED |
| Other information (booster pumps etc) | N/A |

Additional information

| | |
|------------------------------------|----------------|
| Authorities(Custom/immig./health) | 18 OCT. 2018 |
| Security (Stowaways/theft threats) | NIL |
| Spares/Stores/FW supply | NIL |
| Crew change/Shore leave | NIL |
| General comments | SAFELY BERTHED |
| | |
| | |
| Recommendations | |

Master's Name / Date

CAPT. PIOTR MACIEJ MONTWILL / 18 OCT. 2018