

## SAFETY, HEALTH, ENVIRONMENT AND QUALITY MANAGEMENT SYSTEM

## PORT OF CALL HISTORY

## REPORTING FORMS MANUAL

Form: 1.3.1B Date: 02/June/2017 Rev: 1.0 App By: BMM

## Port Feedback

Ship Name	IVS THANDA
Port	NIIHAMA, JAPAN
Terminal & Berth No.	

Port Details	
Anchorage approach	SATISFACTORY
Min. depth at anchorage/Channel	SUFFICIENT FOR ALL LARGE VESSELS
Pilot performance/Tugs condition	GOOD/ADEQUATE
Other information	

Berth Details	
Berth Type	FENDERED/CONCRETE EXTENDED FROM LAND
Minimum depth at Berth/approach/UKC concern	14/SQUARE/NONE
Mooring arrangement	4+2
Berth Restrictions	NO SHORE LEAVE BY LAND- TO BE ARRANGED BY BOAT/AGENT
Berth condition/fendering etc	GOOD
Other information (fendering etc)	

Cargo Operation	
Manifold connections	N/A
Terminal courtsey/co-operation	SATISFACTORY
Safety standard	GOOD
Other information (booster pumps etc)	

Additional information	
Authorities(Custom/immig./health)	ON ARRIVAL
Security (Stowaways/theft threats)	LVL1
Spares/Stores/FW supply	SPECIAL ARRANGEMENT BY BOAT SUPPLY
Crew change/Shore leave	ARRANGEMENT
General comments	
Recommendations	

Master's Name / Date	DANIEL BUDNY 24-12-2019