



SAFETY, HEALTH, ENVIRONMENT AND QUALITY MANAGEMENT SYSTEM

PORT OF CALL HISTORY

REPORTING FORMS MANUAL

Form : 1.3.1B
Date : 02/June/2017
Rev : 1.0
App By : BMM**Port Feedback**

Ship Name	IVS GLENEAGLES
Port	MOMBASA, KENYA
Terminal & Berth No.	GBHL BERTH 4

Port Details

Anchorage approach	VESSEL DRIFTING 10 NM FROM BUOY NO. 2 EFORE PROCEEDING TO INNER ANCHORAGE
Min. depth at anchorage/Channel	N/A
Pilot performance/Tugs condition	GOOD AND SATISFACTORY
Other information	ALL IN GOOD ORDER

Berth Details

Berth Type	BULK CARRIER BERTH
Minimum depth at Berth/approach/UKC concern	13.4 M
Mooring arrangement	(4 + 2) FORWARD AND AFT
Berth Restrictions	NIL
Berth condition/fendering etc	ALL GOOD
Other information (fendering etc)	N/A

Cargo Operation

Manifold connections	VIA SHORE CONVEYOR
Terminal courtesy/co-operation	ALL GOOD
Safety standard	ALL GOOD
Other information (booster pumps etc)	NIL

Additional information

Authorities(Custom/immig./health)	ALL GOOD
Security (Stowaways/theft threats)	ALL GOOD
Spares/Stores/FW supply	ALL GOOD
Crew change/Shore leave	AS SCHEDULED WITHOUT DELAY / ALL GOOD
General comments	ALL GOOD
Recommendations	

Master's Name / Date	CAPT. DENIS R. DIEGO
----------------------	----------------------