



SAFETY, HEALTH, ENVIRONMENT AND QUALITY MANAGEMENT SYSTEM

PORT OF CALL HISTORY

REPORTING FORMS MANUAL

Form : 1.3.1B
Date : 02/June/2017
Rev : 1.0
App By : BMM**Port Feedback**

Ship Name	IVS RAFFLES
Port	MOMBASA, KENYA
Terminal & Berth No.	BERTH NO 3

Port Details

Anchorage approach	NIL
Min. depth at anchorage/Channel	N/A
Pilot performance/Tugs condition	GOOD
Other information	NIL

Berth Details

Berth Type	CONCRETE
Minimum depth at Berth/approach/UKC concern	13
Mooring arrangement	4X2 FWD AND AFT
Berth Restrictions	NIL
Berth condition/fendering etc	GOOD
Other information (fendering etc)	NIL

Cargo Operation

Manifold connections	N/A
Terminal courtesy/co-operation	N/A
Safety standard	YES
Other information (booster pumps etc)	N/A

Additional information

Authorities(Custom/immig./health)	YES
Security (Stowaways/theft threats)	NIL
Spares/Stores/FW supply	NIL
Crew change/Shore leave	YES
General comments	NIL
Recommendations	NIL

Master's Name / Date

CAPT. RICHARD GEDALANGA