



SAFETY, HEALTH, ENVIRONMENT AND QUALITY MANAGEMENT SYSTEM

PORT OF CALL HISTORY

REPORTING FORMS MANUAL

Form : 1.3.1B
Date : 02/June/2017
Rev : 1.0
App By : BMM**Port Feedback**

Ship Name	IVS HIRONO
Port	VENTSPILS, LATVIA
Terminal & Berth No.	BERTH 7A

Port Details	
Anchorage approach	Designated areas to the WNW and NW of the harbour
Min. depth at anchorage/Channel	16.8m
Pilot performance/Tugs condition	Pilot is very professional / Tugs in good condition
Other information	

Berth Details	
Berth Type	Concrete dolphins
Minimum depth at Berth/approach/UKC concern	15m
Mooring arrangement	FWD 4 headlines & 2 spring lines AFT 4 sternlines & 2 spring lines
Berth Restrictions	Nil
Berth condition/fendering etc	well maintained berth / good cell fender
Other information (fendering etc)	

Cargo Operation	
Manifold connections	N/A
Terminal courtesy/co-operation	Good cooperation
Safety standard	Normal
Other information (booster pumps etc)	

Additional information	
Authorities(Custom/immig./health)	Normal port formalities
Security (Stowaways/theft threats)	Security at main gate
Spares/Stores/FW supply	Available
Crew change/Shore leave	Possible
General comments	Vessel berthed starboard side alongside
Recommendations	

Master's Name / Date	R.BARTOSIAK / 25 JAN 2019
----------------------	---------------------------