

SAFETY, HEALTH, ENVIRONMENT AND QUALITY MANAGEMENT SYSTEM

PORT OF CALL HISTORY

Form : 1.3.1B Date : 02/June/2017 Rev : 1.0 App By : BMM

REPORTING FORMS MANUAL

| Port Feedback | |
|---|---|
| Ship Name | IVS BOSCH HOEK |
| Port | TAMATAVE, MADAGASCAR |
| Terminal & Berth No. | MOLE B EAST BERTH |
| Port Details | |
| Anchorage approach | TAMATAVE ANCHORAGE NO 3 |
| Min. depth at anchorage/Channel | 22-25m |
| Pilot performance/Tugs condition | SATISFACTORY |
| Other information | N/A |
| Berth Details | |
| Berth Type | MOLE B EAST BERTH / CONCRETE CONSTRUCTION / PROTECTED WITH MODERN RUBBER FINDERS |
| Minimum depth at Berth/approach/UKC concern | 15.8m / 17.4m / 3.50m |
| Mooring arrangement | 3 + 2 + 2 FWD and AFT / PORT SIDE ALONG SIDE |
| Berth Restrictions | Maximum draught permitted is 13.5m |
| Berth condition/fendering etc | SATISFACTORY |
| Other information (fendering etc) | SATISFACTORY |
| Cargo Operation | |
| Manifold connections | N/A |
| Terminal courtsey/co-operation | SATISFACTORY |
| Safety standard | AS PER PORT ADVICED |
| Other information (booster pumps etc) | N/A |
| Additional information | |
| Authorities(Custom/immig./health) | 26 Oct 19 |
| Security (Stowaways/theft threats) | NIL / ISPS STRICTLY IMPLEMENTED |
| Spares/Stores/FW supply | NIL |
| Crew change/Shore leave | NIL |
| General comments | SAFELY BERTHED |
| Recommendations | ALWAYS SECURE RAT GUARDS AND SHOULD BE VIGILANT IN PORT WATCH.MONITOR MOORING LINES FROM TIME TO TIME. |
| Master's Name / Date | CAPT. MIROSLAW B. KACZMARCZYK / 26 OCT. 2019 |
| | |