



SAFETY, HEALTH, ENVIRONMENT AND QUALITY MANAGEMENT SYSTEM

**PORT OF CALL HISTORY**

REPORTING FORMS MANUAL

Form : 1.3.1B  
Date : 02/June/2017  
Rev : 1.0  
App By : BMM**Port Feedback**

|                      |                    |
|----------------------|--------------------|
| Ship Name            | IVS WENTWORTH      |
| Port                 | Maputo, Mozambique |
| Terminal & Berth No. | Berth no.5         |

**Port Details**

|                                  |   |
|----------------------------------|---|
| Anchorage approach               | Deep approach is via a buoyed channel 56km in length, through the Barra Norte then via the Polana/Xefina Channels. Up river is via the Matola channel to the bulk terminal. |
| Min. depth at anchorage/Channel  | There is one access channels from the open sea leading into Maputo Bay, the North Channel with a limiting depth of 14.3m (Canal do Norte).                                  |
| Pilot performance/Tugs condition | Satisfactory/ 2 Tugs used.  |
| Other information                |   |

**Berth Details**

|   |  |
|---|--|
| Berth Type                                  | Sheltered Berth                                |
| Minimum depth at Berth/approach/UKC concern | Depth at berth 12.0m                           |
| Mooring arrangement                         | Forward and Aft (4+2)                          |
| Berth Restrictions                          | NIL  |
| Berth condition/fendering etc               | Berth is in good condition as well as fenders. |
| Other information (fendering etc)           |  |

**Cargo Operation**

|                                       |                      |
|---------------------------------------|----------------------|
| Manifold connections                  | N/A                  |
| Terminal courtesy/co-operation        | Satisfactory         |
| Safety standard                       | High Safety standard |
| Other information (booster pumps etc) |                      |

**Additional information**

|                                    |   |
|------------------------------------|---|
| Authorities(Custom/immig./health)  | Satisfactory  |
| Security (Stowaways/theft threats) | ISPS Port Compliant/ Provided with 1 Security Personnel each shift for security watch |
| Spares/Stores/FW supply            | FW received   |
| Crew change/Shore leave            | No Crew change/Shore Leave due to COVID-19 Pandemic                                   |
| General comments                   |   |
| Recommendations                    |   |

|                      |   |
|----------------------|---|
| Master's Name / Date | Capt. Benjamin M. Estolas / 30 Mar 2020 |
|----------------------|---|