



SAFETY, HEALTH, ENVIRONMENT AND QUALITY MANAGEMENT SYSTEM

**PORT OF CALL HISTORY**

REPORTING FORMS MANUAL

Form : 1.3.1B  
Date : 02/June/2017  
Rev : 1.0  
App By : BMM**Port Feedback**

Ship Name	IVS NORTH BERWICK
Port	MAPUTO, MOZAMBIQUE
Terminal & Berth No.	BULK Berth No9

**Port Details**

Anchorage approach	
Min. depth at anchorage/Channel	
Pilot performance/Tugs condition	Good / 2 Tugs in Good condition
Other information	Bridge

**Berth Details**

Berth Type	Multi purpose bulk
Minimum depth at Berth/approach/UKC concern	12m / 17.4m / Tidal Sailing
Mooring arrangement	Port Side alongside 4 + 2 Fwd and Aft
Berth Restrictions	
Berth condition/fendering etc	Good
Other information (fendering etc)	

**Cargo Operation**

Manifold connections	N/A
Terminal courtesy/co-operation	Good
Safety standard	Good
Other information (booster pumps etc)	N/A

**Additional information**

Authorities(Custom/immig./health)	Good
Security (Stowaways/theft threats)	Good ( No stowaway & theft threat)
Spares/Stores/FW supply	Available
Crew change/Shore leave	No
General comments	
Recommendations	

Master's Name / Date

Capt. GODFREY G. GIMOTEA / 22 AUG 2020