

SAFETY, HEALTH, ENVIRONMENT AND QUALITY MANAGEMENT SYSTEM

PORT OF CALL HISTORY

REPORTING FORMS MANUAL

Form: 1.3.1B Date: 02/June/2017 Rev: 1.0 App By: BMM

Port Feedback

Ship Name	IVS SPARROWHAWK
Port	MAPUTO MOZAMBIQUE
Terminal & Berth No.	MOZAL BERTH

Port Details	
, monorage approach	Outer Anchorage: Near Buoy No 1N
	to The interpretable of the state of the sta
Pilot performance/Tugs condition	All vessels calling at Manuto must enter port during daylight hours
If Ither intermetion	the extreme S of the country on the N bank of the Espirito Santos

Berth Details	
Berth Type	DRY CARGO BERTH, ALUMINUM
Minimum depth at Berth/approach/UKC concern	12.6M
Mooring arrangement	4+2+2 FWD AND AFT
Berth Restrictions	Maputo-Catembe Bridge: Currently under construction. Vessels should check latest Notices on navigation for the area. When
Berth condition/fendering etc	Berth has adequate fenders.
Other information (fendering etc)	

Cargo Operation		
Manifold connections	N/A	
Terminal courtsey/co-operation	Good and approachable.	
Safety standard	Safety standards are in place.	
Other information (booster pumps etc)	N/A	

Additional information	
Authorities(Custom/immig./health)	Professional and courteous.
Security (Stowaways/theft threats)	ISPS compliant port.
Spares/Stores/FW supply	N/A
Crew change/Shore leave	Sign off crew
General comments	Good sheltered port.
Recommendations	

Master's Name / Date	